

STATE OF NEVADA
 DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY 108791

Log No.
 Permit No.
 Basin 102

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

Please complete this form in its entirety in
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 63763

1. OWNER **Church of Jesus Christ of Latter Day Saints**
 MAILING ADDRESS **P.o. Box 1605**
Fallon, NV 89407-1265

ADDRESS AT WELL LOCATION **5470 Elm Street**
Silver Springs, NV 89429
 Subdivision Name: _____ County: **Lyon**

2. LOCATION **SW¼NW¼ Sec06T17N/ R25E**
 PERMIT/WAIVER NO. **72236/R610**
Issued by Water Resources Parcel. No.

Latitude **39.369098N** UTM E NAD 27
 Longitude **-119.23092W** N NAD 83/WGS 84

3. TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? Yes No
 If yes, what is replacement well NOI? unknown

Is there an existing well log? Yes No
 If yes, what is NDWR well log #? unknown

4. EXISTING WELL CONSTRUCTION
 Depth Drilled _____ Feet Depth Cased _____ Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8"	14.96	.188	unknown	unknown

Existing Perforations:
 Type of perforation unknown
 Size of perforation _____
 From _____ feet to _____ feet
 From _____ feet to _____ feet

5. WATER LEVEL
 Static water level: **60** feet below land surface
 Artesian flow: _____ G.P.M. _____ P.S.I.
 Water Temperature: _____ °F Quality _____

6. Additional Notes or Comments
20% Bentonite was pumped from 124ft to 20ft (16 Bags)
Neat Cement was pumped from 20ft to surface(11bags)

39.369181°N
119.229926°W
NAD 27 (T)

STATE OF NEVADA
 DIVISION OF WATER RESOURCES
 2009 JUN 15 11:11 AM '09

7. WELL PLUGGING PROCEDURE
 Was well cleaned out to total depth? Yes No
 If well was not cleaned out to total depth, please explain why:

Was the well contaminated? Yes No
 Was the casing pulled? Yes No
 Was the casing over drilled? Yes No
 If casing was left in place, please show where additional perforations were made:
 Additional Perforations:
 Type of perforater used: **N/A**
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____

8. WELL PLUGGING MATERIALS

Material Used
20%
 From **124** feet to **20** feet **bentonite** Pumped Poured
Neat
 From **20** feet to **0** feet **Cement** Pumped Poured
 From _____ feet to _____ feet Pumped Poured

Neat Cement Fluid Weight **15.6** lbs/gal
 Bentonite Grout **20** % bentonite
 Date Started **6/2/09**
 Date Completed **6/2/09**

9. DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name **Parsons Drilling, Inc.**
(CONTRACTOR)

Address **P.O. Box 1265**
(CONTRACTOR)
Fallon, NV 89407-1265

Nevada contractor's license number issued by the State Contractor's Board **29064**

Nevada driller's license number issued by the Division of Water Resources, the on-site driller **2307**

Signed WAR
 By driller performing actual drilling on site or contractor

Date **6/10/09**