

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S REPORT

OFFICE USE ONLY
Log No. **108984**
Permit No. _____
Basin **203**

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. **30541**

1. OWNER Wilson Family Trust ADDRESS AT WELL LOCATION Turner Ranch rd
MAILING ADDRESS 146 W. 200 S. milepost 105 - U.S. 93
Enterprise, Ut. 84725 Subdivision Name: _____ County: Lincoln

2. LOCATION SE 1/4 SW 1/4 Sec 13 T 25 N R 67 E Latitude 37° 46.072 UTM E NAD 27
PERMIT/WAIVER No. 65704 012-100-14 Longitude 114° 26.322 N NAD 83/WGS 84

Issued by Water Resources Parcel No. _____

3. WORKED PERFORMED
 New Well Replace Recondition
 Deepen Other

4. PROPOSED USE
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

5. WELL TYPE
 Cable Rotary RVC
 Air Other

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thick-ness
Sand, clay		0	8	8
Clay		8	20	12
Silt, sand, clay		20	56	36
sand, gravel	X	56	74	18
Sand, clay		74	138	64
Sand, gravel	X	138	172	34
Clay		172	200	28

37.767867° N
114.438760° W
NAD 27 (A)

DCNR/DWR RECEIVED

JUN 23 2009

LAS VEGAS OFFICE

9. WELL CONSTRUCTION

Depth Drilled 200 Feet Depth Cased 200 Feet

HOLE DIAMETER (BIT SIZE)

Inches	From	To	Feet
<u>24</u>	0	200	

CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>16</u>	<u>62.4</u>	<u>.375</u>	<u>0</u>	<u>200</u>

Perforations:

Type of perforation factory milled
Size of perforation 3/16 x 2 1/2

From 60 feet to 200 feet

Annular Seal: Yes No

Neat Cement to _____ Pumped Poured
 Cement Grout to _____ Pumped Poured
 Concrete Grout 0 to 52 Pumped Poured
 ≥30% Bentonite Grout to _____ Pumped Poured

Gravel Pack: Yes No to _____ Pumped Poured
Type: 3/4 washed rock

Bentonite Chips: Yes No to _____ Pumped Poured
Type: _____

Date started: Mar 25, 20 08
Date completed: Apr 4, 20 08

7. Water Level

Static water level: 54.8 feet below land surface
Artesian Flow: _____ G.P.M. _____ P.S.I.
Water Temperature: 51.4 °F
Quality: Good

8. WELL TEST DATA

TEST METHOD: Bailer Pump Air Lift

	G.P.M.	Draw Down (Feet Below Static)	Time (Hours)
<u>Air Lift</u>	<u>300</u>		<u>6 hrs</u>
<u>Pump</u>	<u>600</u>	<u>112.4</u>	<u>24 hrs</u>

10. DRILLER'S CERTIFICATION

This well was drilled under my supervision and the reports true to the best of my knowledge.

Name Webber Drilling Contractor
Address PO Box 40 Contractor
Overton, Nv. 89040
Nevada contractor's license number 0025887
issued by the State Contractor's Board
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2238

Signed Bryan Anzabu
By driller performing actual drilling on-site or contractor
Date Apr 30, 2008