

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY
Log No. 109231
Permit No. _____
Basin _____

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 32442

1 OWNER College Park Realty Company
MAILING ADDRESS 6310 San Vicente Blvd #250,
Los Angeles, CA 90048-5447

ADDRESS AT WELL LOCATION 3575 E. Lake Mead Blvd,
Las Vegas, NV
Subdivision Name: MW-4 County: Clark

2 LOCATION NE ¼ SE ¼ Sec 24 T 20S N/S R 61 E
PERMIT/WAIVER No. N/A 139-24-701-009
Issued by Water Resources Parcel No.

Latitude 36° 11' 27" UTM E NAD 27
Longitude 115° 05' 19" N NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? No
If yes, what is replacement well NO? _____

Is there an existing well log? No
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 29 Feet Depth Cased 29 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4.5	10.79	.237	0	29

Existing Perforations:

Type of perforation	Factory
From <u>9</u> feet to <u>29</u> feet	<u>0.02 φ</u>
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no

If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no

If casing was left in place, please show where additional perforations were made:
Additional Perforations: _____

Type of perforator used: N/A

From	feet to	feet	Number of perfs per linear foot
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____

5 WATER LEVEL
Static water level 15.75 feet below land surface
Artesian flow N/A G.P.M. N/A P.S.I.
Water temperature N/A °F Quality Good

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From <u>0</u>	feet to <u>29</u>	feet	Bentonite Grout	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments
Grouted wells, pulled casing, concrete cuped

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout 20 % bentonite
Date Started 10/22/2009
Date Completed 10/22/2009

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name WDC Exploration & Wells Contractor
Address 570 Corinthian Way, N. Las Vegas, NV 89030 Contractor

Nevada contractor's license number issued by the State Contractor's Board 0012852

Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2371

Signed _____
Date 10/30/2009
By driller (certifying actual drilling on site) or contractor

