

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**

Log No. 109232  
 Permit No. \_\_\_\_\_  
 Basin \_\_\_\_\_

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 32442

1 OWNER College Park Realty Company  
 MAILING ADDRESS 6310 San Vicente Blvd #250,  
 Los Angeles, CA 90048-5447

ADDRESS AT WELL LOCATION 3575 E. Lake Mead Blvd,  
 Las Vegas, NV  
 Subdivision Name: MW-3 County: Clark

2 LOCATION NE 1/4 SE 1/4 Sec 24 T 20S NWS R 61 E  
 PERMIT/WAIVER No. N/A 139-24-701-009  
Issued by Water Resources Parcel No.

Latitude 36° 11' 32" UTM E  NAD 27  
 Longitude 115° 05' 9.14" N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? No  
 If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? No  
 If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
 Depth Drilled 30 Feet Depth Cased 30 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4.5	10.79	.237	0	30

Existing Perforations:

Type of perforation	Factory
Size of perforation	0.020
From <u>10</u> feet to <u>30</u> feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	

7 WELL PLUGGING PROCEDURE  
 Was well cleaned out to total depth?  yes  no  
 If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
 Was the casing pulled?  yes  no  
 Was the casing over drilled?  yes  no  
 If casing was left in place, please show where additional perforations were made:  
 Additional Perforations: N/A

Type of perforater used:	N/A
From _____ feet to _____ feet	Number of perfs per linear foot _____
From _____ feet to _____ feet	Number of perfs per linear foot _____
From _____ feet to _____ feet	Number of perfs per linear foot _____
From _____ feet to _____ feet	Number of perfs per linear foot _____
From _____ feet to _____ feet	Number of perfs per linear foot _____
From _____ feet to _____ feet	Number of perfs per linear foot _____

5 WATER LEVEL  
 Static water level 14.85 feet below land surface  
 Artesian flow N/A G.P.M. N/A P.S.I.  
 Water temperature N/A °F Quality Good


8 WELL PLUGGING MATERIALS

From	To	Material Used	Pumped	Poured
0	30	Bentonite Grout	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
Grouted wells, pulled casing, concrete cuped

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
 Bentonite Grout 20 % bentonite  
 Date Started 10/22/2009  
 Date Completed 10/22/2009

9 DRILLER'S CERTIFICATION  
 This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
 Name WDC Exploration & Wells Contractor  
 Address 570 Corinthian Way, N. Las Vegas, NV 89030 Contractor  
 Nevada contractor's license number 0012852 issued by the State Contractor's Board  
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2371  
 Signed [Signature] Driller performing actual drilling on site or contractor  
 Date 10/30/2009



USE ADDITIONAL SHEETS IF NECESSARY

(Rev. 05-06)