STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 109255
Permit No.
Basin 105

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 58678

1 OWNER Indian Hills General Improvement Dist.
MAILING ADDRESS 3440 James Lee Park Road #A
(NW) Carson City, NV. 89705

ADDRESS AT WELL LOCATION 1/4 mile northwest of James Lee Park
Subdivision Name: County: Douglas

2 LOCATION Lot ¼ SW ¼ Sec 7 T 14 N/S R 20 E/W
PERMIT/WAIVER No. 43685 Issued by Water Resources Parcel No.

Latitude 39°5.344N
Longitude 119°47.283W
UTM E N
☐ NAD 27 ☒ NAD 83/WGS 84

3 TYPE OF WELL
☐ Domestic ☐ Irrigation ☐ Test
☒ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? n/a
If yes, what is replacement well NOI?

Is there an existing well log? yes
If yes, what is NDWR well log #? 20185

4 EXISTING WELL CONSTRUCTION
Depth Drilled 345 Feet Depth Cased 345 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8		.188	+2	345

Existing Perforations:
Type of perforation mill slot
Size of perforation Mar-32

From	80	feet to	120	feet
From	150	feet to	200	feet
From	210	feet to	276	feet
From	300	feet to	345	feet
From		feet to		feet

5 WATER LEVEL
Static water level 73.6 feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature °F Quality

6 Additional Notes or Comments

Removed 294' of 2" drop pipe with submersible pump. Measured static water level at 73.6' and depth of well at 344'. Installed Mills Knife and perforated 6 rows per foot from 80' to surface. Installed 340' of 2" tremme pipe and the following week, pumped in 7 yards of neat cement from bottom of well back to surface. Actual well volume is 4.5 yards.

~~30.089158°N~~ 39.089158N
119.787036°W
NAD 27 (TA)

STATE ENGINEER'S OFFICE
2009 NOV 23 AM 11:53

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☒ yes ☐ no
If well was not cleaned out to total depth, please explain why:

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:

Additional Perforations:
Type of perforater used: Mills Knife

From	80	feet to	surface	feet	Number of perfs per linear foot 6
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

					Material Used		
From	345	feet to	surface	feet	neat cement	☒ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured

Neat Cement Fluid Weight 14.7 lbs/gal
Bentonite Grout % bentonite
Date Started 11/6/2009
Date Completed 11/13/2009

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Carson Pump, LLC (Contractor)
Address P.O. Box 20159 (Contractor)
Carson City, NV. 89721
Nevada contractor's license number issued by the State Contractor's Board 0039920A
Nevada driller's license number issued by the Division of Water Resources, the original driller 2265
Signed (By driller performing actual drilling on site or contractor)
Date 11/16/2009

(Rev. 06-06) USE ADDITIONAL SHEETS IF NECESSARY