

Well #2

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY 109312

Log No.
Permit No.
Basin

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 64373

1. OWNER IDAHOAN FOODS
ADDRESS AT WELL LOCATION IDAHOAN FOODS, 1 POTATO RD., WINNEMUCCA, NEVADA
MAILING ADDRESS 1 POTATO RD., WINNEMUCCA, NV. 89445

2. LOCATION NE 1/4 SW 1/4 Sec 1 T 35N N/S R 37 E
Latitude 40.934466 UTM E
Longitude -117.768974 N
PERMIT/WAIVER No. NEV89012 10-355-16
Parcel No.
Subdivision Name:
County: Humboldt

3. TYPE OF WELL
Domestic, Irrigation, Test, Municipal/Industrial, Monitor, Stock
Is this well being plugged because a replacement well was drilled? YES
If yes, what is replacement well NOI? 64372
Is there an existing well log? YES
If yes, what is NDWR well log #? 48780

4. EXISTING WELL CONSTRUCTION
Depth Drilled 88 Feet
Depth Cased 85 Feet

Table with columns: Size O.D. (Inches), Weight/Ft. (Pounds), Wall Thickness (Inches), From (Feet), To (Feet). Rows for SCH 80 PVC casing.

Existing Perforations:
Type of perforation: FACTORY SCREEN
Size of perforation: 0.02
From 50 feet to 80 feet

7. WELL PLUGGING PROCEDURE

Was well cleaned out to total depth? yes [X] no
If well was not cleaned out to total depth, please explain why:

INSERTED A MEASURING PROBE TO BOTTOM OF WELL. THERE WAS NO DEBRIS IN WELL

Was the well contaminated? yes [] no [X]
Was the casing pulled? yes [] no [X]
Was the casing over drilled? yes [] no [X]

If casing was left in place, please show where additional perforations were made:
Additional Perforations:

Type of perforater used: NONE
From ... feet to ... feet
Number of perfs per linear foot

5. WATER LEVEL
Static water level 54 feet below land surface
Artesian flow G.P.M. P.S.I.
Water temperature <85 °F Quality GOOD

8. WELL PLUGGING MATERIALS

Material Used
From 0 feet to 85 feet NEAT CEMENT [X] Pumped [] Poured
From ... feet to ... feet [] Pumped [] Poured

6. Additional Notes or Comments
TOOK MORE GROUT THAN VOLUME CALCULATED
ALSO, CLIENT INDICATED HAVING PROBLEMS GETTING SAMPLING EQUIPMENT TO THE BOTTOM OF THE WELL. THAT WAS THE REASON FOR ABANDON AND A REPLACEMENT WELL.

Neat Cement Fluid Weight 15.5 lbs/gal
Bentonite Grout % bentonite
Date Started 10/21/2009
Date Completed 10/21/2009

Handwritten coordinates: 40.934563° N, 117.768010° W, NAD 27 (1A)

9. DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name HAZ-TECH DRILLING, INC. Contractor

Address PO BOX 940 Contractor

MERIDIAN, ID. 83680
Nevada contractor's license number issued by the State Contractor's Board 0038018
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2137

Signed [Signature] By driller performing actual drilling on site or contractor
Date 11-12-09