

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 109342  
Permit No. \_\_\_\_\_  
Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 35126

1 OWNER Rebel Land LLC % S Siam ADDRESS AT WELL LOCATION 3380 E. Flamingo RD  
MAILING ADDRESS 4390 Ambercrest PI MW-5  
Thousand Oaks, CA, 91362-5644 Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION SE ¼ SE ¼ Sec 13 T 21S N/S R 61 E Latitude 36 06'56.87"N UTM E  NAD 27  
PERMIT/WAIVER No. 16213802023 Longitude 115 06'04.33W N  NAD 83/WGS 84  
issued by Water Resources Parcel No.

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? No  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? No  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled n/a Feet Depth Cased 25 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4.5	2.06	Sch 40	0	25

Existing Perforations:

Type of perforation	Factory Slotted
Size of perforation	0.02
From <u>5</u> feet to <u>25</u> feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	

5 WATER LEVEL  
Static water level 12 feet below land surface  
Artesian flow  G.P.M. \_\_\_\_\_ P.S.I. \_\_\_\_\_  
Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_

6 Additional Notes or Comments  
Knocked out bottom of well and tremie bentonite grout from the bottom up then pulled casing

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

Type of perforater used:	Number of perfs per linear foot
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____

8 WELL PLUGGING MATERIALS

Material Used			
From <u>0</u> feet to <u>25</u> feet	Bentonite Grout	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout 28.5 % bentonite  
Date Started 10/27/2009  
Date Completed 10/27/2009

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name WDC Exploration & Wells  
Contractor  
Address 570 Corinthian Way  
Contractor  
N. Las Vegas, NV, 89030  
Nevada contractor's license number issued by the State Contractor's Board 0012852  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2381  
Signed [Signature]  
By driller performing actual drilling on site or contractor  
Date 11-4-09