

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 109394
Permit No. _____
Basin _____

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

1 OWNER Bellanger Family Trust et al
MAILING ADDRESS 801 Searles Ave LV NV 89101

NOTICE OF INTENT NO. 32196
ADDRESS AT WELL LOCATION 801 Searles Ave Las Vegas NV 8901
Subdivision Name: _____ County: CLAYTON

2 LOCATION NW 1/4 Sec 26 T 20 N R 61 E
PERMIT/WAIVER No. 8-00009 V3926102003
Issued by Water Resources Parcel No. _____

Latitude 36.110992 UTM E _____
Longitude 115.075232 N _____
 NAD 27
 NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? _____
Is there an existing well log? _____
If yes, what is replacement well NO? _____
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled _____ Feet Depth Cased _____ Feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

| EXISTING CASING SCHEDULE | | | | |
|--------------------------|--------------------|-------------------------|-------------|-----------|
| Size O.D. (Inches) | Weight/Ft (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
| 2 1/2 | PVC | SEH 40 | 3 | 25 |
| | | | | |
| | | | | |

Existing Perforations:

| From | Type of perforation | Size of perforation | feet to | feet |
|------|---------------------|---------------------|---------|------|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

5 WATER LEVEL
Static water level 14.5 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ ° F Quality _____

6 Additional Notes or Comments

Vault was in ground because it was 4' x 3' x 2'

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made: _____

Additional Perforations:

| Type of perforator used: | | | |
|--------------------------|---------|------|---------------------------------|
| From | feet to | feet | Number of perfs per linear foot |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

8 WELL PLUGGING MATERIALS

| Material Used | | | |
|---------------|---------|------|--|
| From | feet to | feet | Material |
| 3 | feet to | 25 | 3/4" Hole Reuse <input type="checkbox"/> Pumped <input checked="" type="checkbox"/> Poured |
| | feet to | | |

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite
Date Started 9-23-09
Date Completed 9-23-09

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Eagle Drilling Contractor

Address 7150 Placid Street Contractor

Las Vegas NV 89119

Nevada contractor's license number _____
Issued by the State Contractor's Board 51266

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2097

Signed _____
By driller performing actual drilling on site or contractor

Date 9-28-09

SEP 28 2009

USE ADDITIONAL SHEETS IF NECESSARY

LAS VEGAS