

12

# STATE OF NEVADA DIVISION OF WATER RESOURCES WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 109396  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

1 OWNER Bellanger Family Trust et al ADDRESS AT WELL LOCATION 801 Searles Ave NOTICE OF INTENT NO. 32196  
MAILING ADDRESS 801 Searles Ave LV NV 89101 Las Vegas NV 8901

2 LOCATION NW 1/4 Sec 26 T 20 N R 61 E Latitude 36.110978 UTM E \_\_\_\_\_ NAD 27   
PERMIT/WAIVER No. 8.000004 13926102.003 Longitude 115.075192 N \_\_\_\_\_ NAD 83/WGS 84   
Issued by Water Resources Parcel No. \_\_\_\_\_ County: Clark

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? \_\_\_\_\_  
Is there an existing well log? \_\_\_\_\_  
If yes, what is replacement well NOR? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	Feet	
EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2 1/2</u>	<u>PVC</u>	<u>5/8 x 40</u>	<u>0</u>	<u>25</u>

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Existing Perforations:  
Type of perforation \_\_\_\_\_  
Size of perforation \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations: \_\_\_\_\_

5 WATER LEVEL  
Static water level 13.5 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

Type of perforator used:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

6 Additional Notes or Comments  
WELL WAS IN GROUND  
BECAUSE IT WAS  
4' x 3' x 2'

8 WELL PLUGGING MATERIALS  
Material Used  
From 0 feet to 25 feet 3/4 Hole Reel  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 9-23-09  
Date Completed 9-23-09

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name EAGLE Drilling Contractor  
Address 7150 PLacid Street Contractor  
Las Vegas NV 89119  
Nevada contractor's license number \_\_\_\_\_  
Issued by the State Contractor's Board 51266  
Nevada driller's license number Issued by the Division of Water Resources, the on-site driller 2097  
Signed \_\_\_\_\_  
By driller performing actual drilling on site of contractor  
Date 9-28-09