

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 110085
Permit No. _____
Basin 105

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK
(and Margaret)

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. **64421**

1. OWNER **Pedro Villalobos** ADDRESS AT WELL LOCATION **507 Green Acres Dr. Gardnerville, NV 89460**
MAILING ADDRESS **507 Green Acres Dr. Gardnerville, NV 89460** Subdivision Name: _____ County: **Douglas**

2. LOCATION **NW1/4NE1/4 Sec26T12N/ R19E** Latitude **38.87972** UTM E NAD 27
PERMIT/WAIVER NO. **1219-26-001-032** Longitude **119.81496** N NAD 83/WGS 84
Issued by Water Resources Parcel No. _____

3. TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? Yes No
If yes, what is replacement well NOI? **64420**
Is there an existing well log? Yes No
If yes, what is NDWR well log #? **14123**

4. EXISTING WELL CONSTRUCTION
Depth Drilled **122?** Feet Depth Cased **122?** Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8 5/8	19	.188	0	82
6 5/8	13	.188	80	87?

Existing Perforations:
Type of perforation **Factory**
Size of perforation **1/8 x 3**
From **60** feet to **87** feet
From _____ feet to _____ feet

5. WATER LEVEL
Static water level: **0** feet below land surface
Artesian flow: **1** G.P.M. P.S.I.
Water Temperature: **cold** °F Quality **Not Tested**

6. Additional Notes or Comments
Two other companies had tried to clean this well to 122'. Both companies were not able to get beyond 87'. One company spent several days bailing with no success and the other company blew the fill down to 87'. We also cleaned the well to 87', but were not able to go further. We believe the casing was never greater than 87'.

38.880° N
119.814° W NAD27 D.D.

7. WELL PLUGGING PROCEDURE

Was well cleaned out to total depth? Yes No
If well was not cleaned out to total depth, please explain why:
The well was cleaned to 87'. At that point, we couldn't clean further due to sand coming into well. We believe the casing was never greater than 87'.
Was the well contaminated? Yes No
Was the casing pulled? Yes No
Was the casing over drilled? Yes No
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used:
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

8. WELL PLUGGING MATERIALS

Material Used
Bentonit
From **87** feet to **20** feet **e** Pumped Poured
From **20** feet to **0** feet **Neat** Pumped Poured
From _____ feet to _____ feet Pumped Poured
Neat Cement Fluid Weight **15** lbs/gal
Bentonite Grout **20** % bentonite

Date Started **7-17-09**
Date Completed **7-17-09**

9. DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name **Bruce MacKay Pump & Well Service, Inc.** (CONTRACTOR)
Address **1600 Mt. Rose Hwy** (CONTRACTOR)
Reno, NV 89511
Nevada contractor's license number issued by the State Contractor's Board **23096**
Nevada driller's license number issued by the Division of Water Resources, the on-site driller **923**
Signed R. Bruce MacKay
By driller performing actual drilling on site or contractor
Date **7-21-09**