

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 11550
Permit No. _____
Basin 30A

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. #65385

1 OWNER KINGS RIVER RANCH ADDRESS AT WELL LOCATION 129 Kings River Rd
MAILING ADDRESS 129 Kings River Road OROVADA, NV 89425
OROVADA, NV 89425 Subdivision Name: A-Block County: HUMBOLDT

2 LOCATION NE 1/4 NE 1/4 Sec 27 T 46 N/S R 33 E Latitude N 41° 50' 48.6" UTM E NAD 27
PERMIT/WAIVER No. 16816 Longitude W 118° 14' 40.5" N NAD 83/WGS 84

Issued by Water Resources Parcel No. _____

3 TYPE OF WELL Domestic Irrigation Test Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? N.O. Is there an existing well log? N.O.

If yes, what is replacement well NOI? _____ If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	Feet
EXISTING CASING SCHEDULE			
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet) To (Feet)
<u>48</u>		<u>3/8</u>	<u>0 12</u>

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth? yes no

If well was not cleaned out to total depth, please explain why: IT WAS DETERMINED THIS WAS NOT A WELL.

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
<u>NONE</u>				

Additional Perforations:

Type of perforator used:	From	feet to	feet	Number of perfs per linear foot
<u>NA</u>				

5 WATER LEVEL

Static water level NA feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS

Material Used	From	feet to	feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
<u>NA</u>				

6 Additional Notes or Comments

WE DRILLED A HOLE IN BOTTOM OF TANK, WITH STEVE DELSOLATO ON THE SITE TO OBSERVE.

THERE WAS NO WELL HERE AT ALL ONLY A CISTERN TYPE SYSTEM FOR PUMPING WATER FROM A COLLECTION POND. STEVE TOOK PHOTOS AND SAID WE COULD PULL IT AND BACK FILL USING ONLY DIRT.

NAD-27 GPS: 41.846936°N } NW/46 Sec 26
118.243593°W }

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout NA % bentonite NA

Date Started 7/26/10
Date Completed 8/3/10

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name KINGS RIVER RANCH Contractor
Address 129 Kings River Rd Contractor
OROVADA, NEVADA 89425

Nevada contractor's license number _____
issued by the State Contractor's Board

Nevada driller's license number issued by the
Division of Water Resources, the on-site driller 1712

Signed Mike M. Dinech
By driller performing actual drilling on site or contractor

Date 8-18-10