

THIS BORING LOG IS FOR VIKING'S INTERNAL PURPOSES ONLY. IT DOES NOT REPRESENT INFORMATION PROVIDED BY A SOILS ENGINEER.



LOG FOR BORING NO. <i>dep. team well # 5</i>		JOB NAME: <i>LV PAVING</i>			
DATE STARTED <i>4-19-2010</i>	DATE COMPLETED <i>4-19-10</i>	LOGGED BY <i>Ed</i>	DRILLED BY <i>Ed</i>	TYPE OF DRILL RIG <i># 31</i>	JOB NO. <i>5970</i>
DEPTH OF HOLE <i>30'</i>	DIAMETER OF HOLE <i>24"</i>	CASING <i>8"</i>	PERFORATIONS <i>20'</i>	SAMPLING METHOD	ELEVATION
LOCATION <i>358+00</i>				DRILLERS NOTES: <i>4-20-2010</i> <i>water static at 9'</i> <i>water flowed into the hole considerably more than station 371+00</i>	
DEPTH	SAMPLES	GRAPHIC	DESCRIPTION		
0'			<i>Rocky clay</i>		
10'			<i>clay</i>		
10'			<i>meist silty clay</i>		
20'			<i>silty clay</i>		
20'			<i>clay</i>		
30'					
40'					
50'					
60'					
70'					
80'					
90'					
100'					

DCNR/DWR
RECEIVED

JUN 28 2010

LAS VEGAS OFFICE

APR 26 2010