

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 111909  
Permit No. \_\_\_\_\_  
Basin 212

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 33842

1 OWNER Basic Environmental Co. LLC ADDRESS AT WELL LOCATION Unincorp County  
MAILING ADDRESS 875 W. WARM SPRINGS RD  
HENDERSON NV 89011 Subdivision Name: \_\_\_\_\_ County: CLARK

2 LOCATION NW¼ SE ¼ Sec 11 T 22 N R 62 E Latitude 36.047987 UTM E  NAD 27  
PERMIT/WAIVER No. 118-11-501-006 Longitude 115.017041 N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? yes  
If yes, what is NDWR well log #? 109289

4 EXISTING WELL CONSTRUCTION

Depth Drilled 50 Feet Depth Cased 50 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4</u>		<u>40</u>	<u>25</u>	<u>0</u>

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:

Type of perforation machine  
Size of perforation .020

From	feet to	feet	feet
<u>50</u>	<u>25</u>		

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL

Static water level 0 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	Pumped	Poured
<u>50</u>	<u>0</u>		<u>Quick Grout</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments

well was NOT ACCESSABLE TO RIG & CASING WAS NOT PULLED OR DISPERATED DROPPED A POINTY BAR & SECURED TO A ROPE TO PUNCTURE BOTTOM CAP & ABOVE IT UP & PUT CEMENT CAP FROM 4 TO 0

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 5/20/10  
Date Completed 5/20/10

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Shawn Sears Contractor  
Address 7150 PLACITA L.V. NV. 89119 Contractor

DCNR/DWR  
RECEIVED  
JUN 02 2010

Nevada contractor's license number issued by the State Contractor's Board 2399 51266  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2399 1088

Signed Shawn Sears By driller performing actual drilling on site or contractor  
Date 5/24/10

LAS VEGAS OFFICE