

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
Log No. 111966  
Permit No. 104  
Basin 104

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 64386

1. OWNER NDEP ADDRESS AT WELL LOCATION EAGLE GAS, 2152 N. CARSON STREET  
MAILING ADDRESS 901 S. STEWART ST., STE. 4001 CARSON CITY, NV.  
CARSON CITY, NV. 89701

2. LOCATION SW 1/4 NW 1/4 Sec 8 T 15N N/S/R 20 E Latitude 39.18014° UTM E  NAD 27  
PERMIT/WAIVER No. 1-000030 001-032-04 Longitude 119.76731° N  NAD 83/WGS 84  
Issued by Water Resources Parcel No. Subdivision Name: County: Carson City

3. TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NOI?  
Is there an existing well log? YES  
If yes, what is NDWR well log #? 109633

4. EXISTING WELL CONSTRUCTION  
Depth Drilled 20 Feet Depth Cased 20 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
1	PVC	SCH 40	0	5

Existing Perforations:

Type of perforation	Size of perforation	From	To
FACTORY	0.01	5 feet	20 feet

5. WATER LEVEL  
Static water level 10 feet below land surface  
Artesian flow   G.P.M. P.S.I.  
Water temperature <85 °F Quality  

6. Additional Notes or Comments  
GROUTED PVC IN PLACE CAUSE WELL LOCATION WAS UNDERNEATH POWER LINES. TRIMMIE GROUTED FROM BOTTOM TO TOP.  
WELL NUMBER WAS MW-5  
NAD-27 GPS  
39.180270° N  
119.766267° W  
Plugging of Well Log  
# 109633

7. WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why:  
GROUTED IN PLACE. WELL WAS LOCATED UNDER POWER LINES

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations: NONE  
Type of perforater used:  
From   feet to   feet Number of perfs per linear foot    
From   feet to   feet Number of perfs per linear foot    
From   feet to   feet Number of perfs per linear foot    
From   feet to   feet Number of perfs per linear foot    
From   feet to   feet Number of perfs per linear foot    
From   feet to   feet Number of perfs per linear foot  

8. WELL PLUGGING MATERIALS

From	To	Material Used	Method
0	20	NEAT CEMENT	<input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

Neat Cement Fluid Weight 16 lbs/gal  
Bentonite Grout 3 % bentonite  
Date Started 8/14/2010  
Date Completed 8/14/2010

9. DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name HAZ-TECH DRILLING, INC. Contractor  
Address PO BOX 940 Contractor  
MERIDIAN ID. 83680  
Nevada contractor's license number issued by the State Contractor's Board 0038018  
Nevada driller's license number issued by the Division of Water Resources, on-site driller 2412-M-LTD  
Signed [Signature] by driller performing actual drilling on site or contractor  
Date 9/7/10

USE ADDITIONAL SHEETS IF NECESSARY

(Rev. 12-05)