

PLUGGING WELL
LOG # 110677

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 112229
Permit No.
Basin 108

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 65557

1 OWNER Campbell Constuction ADDRESS AT WELL LOCATION 56 Hwy 95 A
MAILING ADDRESS 36 Glen Carran Circle Mason Valley #108
Sparks NV 89431 134N Subdivision Name: County: LYON

2 LOCATION SE ¼ NW ¼ Sec 10 T 134N N/S/R 25 E Latitude A See list UTM E NAD 27
PERMIT/WAIVER No. DEW-84 001-561-01 Longitude N NAD 83/WGS 84
Issued by Water Resources Parcel No.

3 TYPE OF WELL Drwater Is this well being plugged because a replacement well was drilled? no Is there an existing well log? yes
 Domestic Irrigation Test Municipal/Industrial Monitor Stock If yes, what is replacement well NOI? If yes, what is NDWR well log #? 110677
see list

4 EXISTING WELL CONSTRUCTION
Depth Drilled 30 Feet Depth Cased 30 Feet

EXISTING CASING SCHEDULE

| Size O.D. (Inches) | Weight/Ft (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
|--------------------|--------------------|-------------------------|-------------|-----------|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Existing Perforations:
Type of perforation
Size of perforation
From feet to feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

5 WATER LEVEL
Static water level 5" feet below land surface
Artesian flow G.P.M. P.S.I.
Water temperature °F Quality

6 Additional Notes or Comments
Pumped neat cement into casing and pulled the casing.
Left cement down to 3'-4' and filled top with dirt at customers
request.

#6PS
390021.97 390022.06
119.1020.29 119.1020.57
390022.12 390022.12
119.1020.92 119.1021.11
390022.00 390021.95
119.1021.37 119.1020.04

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: Wells clean to the bottom

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:

Additional Perforations:
Type of perforator used:
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot

8 WELL PLUGGING MATERIALS
Material Used
From 3to4 feet to 29 feet Neat Cement Pumped Poured
From feet to feet Pumped Poured

Neat Cement Fluid Weight lbs/gal
Bentonite Grout % bentonite
Date Started Sept 22 2010
Date Completed Sept 23 2010

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Blain Well Drilling Contractor
Address PO Box 1255 Carson City NV 89702 Contractor
Nevada contractor's license number
issued by the State Contractor's Board 46498
Nevada driller's license number issued by the
Division of Water Resources, the on-site driller 2134
Signed [Signature]
Date Sept 23 2010
By driller performing actual drilling on site or contractor

2010 SEP 23 11:33:33
USE ADDITIONAL SHEETS IF NECESSARY
39.006125°N
119.171316°W
NAD 27 (T)