

APN #  
1318-27-001-007

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 112413  
Permit No.  
Basin 090

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 66098

1 OWNER Desert Palace, Inc.  
MAILING ADDRESS One Caesar's Palace Drive  
Las Vegas, NV 89109

ADDRESS AT WELL LOCATION Facility ID: 2-000031 SP-1  
55 US Highway 50 Steline, NV  
Subdivision Name: County: Douglas

2 LOCATION SE 1/4 NE 1/4 Sec 27 T 13N N/S R 18 E  
PERMIT/WAIVER No. 07-04-014  
Issued by Water Resources (Old) Parcel No.

Latitude 38.96171 UTM E  NAD 27  
Longitude 119.93847 N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? No  
If yes, what is replacement well NO?

Is there an existing well log?  
If yes, what is NDWR well log #?

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 25 Feet Depth Cased 25 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why:

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2		Sch 40	0	25

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

Existing Perforations:

Type of perforation	Slot
Size of perforation	0.02
From 23 feet to 25 feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	

5 WATER LEVEL  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS  
Material Used  
From 0 feet to 25 feet Cement  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

6 Additional Notes or Comments  
Pressure Grout 25' 2" well and drillout top 3'

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 9/1/2010  
Date Completed 9/1/2010

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Cascade Drilling, L.P. Contractor  
Address 3632 Omeq Circle Contractor  
Rancho Cordova, CA 95742  
Nevada contractor's license number issued by the State Contractor's Board 73966  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1935  
Signed \_\_\_\_\_  
Date 9/16/2010

(Rev 05-06)

USE ADDITIONAL SHEETS IF NECESSARY  
38.961802°N  
119.937456°W  
NAD 27 (T)