

**ORIGINAL**

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
Log No. 112560  
Permit No. 78860  
Basin 036

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 66393

1 OWNER RUBY PIPELINE, LLC. ADDRESS AT WELL LOCATION NORTH OF ELKO ON THE ROAD TO TUSCARORA, NV M.P. 351.93  
 MAILING ADDRESS P.O. Box 1087 COLORADO SPRINGS Colorado Springs, CO 80944 *Subdivision Name:* \_\_\_\_\_ *County:* Elko

2 LOCATION NE ¼ SE ¼ Sec 2 T 36N N/S R 51 E Latitude 41° 12' 46.41" N UTM E  NAD 27  
 PERMIT/WAIVER No. 78860 Longitude 116° 12' 05.35" W N  NAD 83/WGS 84  
*issued by Water Resources* *Parcel No.* \_\_\_\_\_

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock  
 Is this well being plugged because a replacement well was drilled? NO  
 If yes, what is replacement well NOI? \_\_\_\_\_  
 Is there an existing well log? YES  
 If yes, what is NDWR well log #? N/A

4 EXISTING WELL CONSTRUCTION  
 Depth Drilled 1100' Feet Depth Cased 0' Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)

Existing Perforations:

Type of perforation	Size of perforation	From	To
N/A	N/A		

7 WELL PLUGGING PROCEDURE  
 Was well cleaned out to total depth?  yes  no  
 If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
 Was the casing pulled?  yes  no  
 Was the casing over drilled?  yes  no  
 If casing was left in place, please show where additional perforations were made:  
 Additional Perforations:  
 Type of perforator used: \_\_\_\_\_  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
 From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
 Static water level N/A feet below land surface  
 Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
 Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	To	Material Used	Method
0'	20'	NEAT CEMENT	<input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured
20'	1100'	BENTONITE GROUT	<input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

6 Additional Notes or Comments  
 THIS WAS A BOREHOLE THAT WAS NO GOOD  
 ACCORDING TO OUR SAMPLES AND E-LOG.  
 WE WENT AHEAD AND ABANDONED IT TO STATE REGS.  
 THE BOREHOLE WAS SUBMITTED UNDER NOI #66395

**Plugging of Well Log 112559**

NAD 83 GPS  
41.212982° N  
116.201486° W

NAD 27  
41.212983° N  
116.200565° W

Neat Cement Fluid Weight 15 LBS lbs/gal  
 Bentonite Grout 20% % bentonite  
 Date Started 21-Nov  
 Date Completed 21-Nov

9 DRILLER'S CERTIFICATION  
 This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
 Name Hydro Resources - West Contractor  
 Address 4975 W. Winnemucca Blvd. Contractor  
Winnemucca, NV 89445  
 Nevada contractor's license number issued by the State Contractor's Board 56797  
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller # 1713  
 Signed [Signature]  
 Date 11/30/2010