

STATE OF NEVADA
 DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
 Log No. 112570
 Permit No. _____
 Basin 137B

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

Please complete this form in its entirety in
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 65778

1. OWNER Round Mountain Mine 2006-3 ADDRESS AT WELL LOCATION #1 Mine Road
 MAILING ADDRESS PO Box 480 Round Mountain, NV. 89045 Round Mountain, NV.
 Subdivision Name: _____ County: NYE

2. LOCATION NW 1/4 Sec 19 T16N R43E (see below) Latitude _____ UTM E 492966 NAD 27
 PERMIT/WAIVER NO. M/O - 1402 Longitude _____ N 4283565 NAD 83/WGS 84
 Issued by Water Resources Parcel No. _____

3. TYPE OF WELL Is this well being plugged because a replacement well was drilled? Yes No
 Domestic Irrigation Test Municipal/Industrial Monitor Stock
 If yes, what is replacement well NOI? _____ Is there an existing well log? Yes No
 If yes, what is NDWR well log #? 101437

4. EXISTING WELL CONSTRUCTION
 Depth Drilled 600 Feet Depth Cased 600 Feet
 EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6.625	9.29	.156	+1	20
2	3.65	.125	+2	600

Existing Perforations:
 Type of perforation Vertical
 Size of perforation .020

From	feet to	feet
<u>100</u>	<u>600</u>	<u>feet</u>
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

5. WATER LEVEL
 Static water level: 60.77 feet below land surface
 Artesian flow: _____ G.P.M. _____ P.S.I.
 Water Temperature: Hot °F Quality Slightly murky

6. Additional Notes or Comments
NAD-27 GPS: 38.702551°N
117.080892°W
Location: NW NE Sec 30. 10N 44E

Materials Used:
13.6 cu ft Neat Cement

NOV 23 2010 10:00 AM
 RECEIVED
 DIVISION OF WATER RESOURCES
 STATE OF NEVADA

Plugging of Well Log 101437

7. WELL PLUGGING PROCEDURE
 Was well cleaned out to total depth? Yes No
 If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? Yes No
 Was the casing pulled? Yes No
 Was the casing over drilled? Yes No
 If casing was left in place, please show where additional perforations were made:
 Additional Perforations:
 Type of perforator used: N/A

From	feet to	feet	Number of perfs per linear foot
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

8. WELL PLUGGING MATERIALS
 Material Used

From	feet to	feet	Material	Pumped	Poured
<u>0</u>	<u>600</u>	<u>feet</u>	<u>Cement</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>
_____	_____	_____	_____	<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight: 15.6 lbs/gal
 Bentonite Grout: _____ % bentonite

Date Started December 11, 2010
 Date Completed December 11, 2010

9. DRILLER'S CERTIFICATION
 This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
 Name Boart Longyear (CONTRACTOR)
 Address 2745 California Ave (CONTRACTOR)
SLC., UT. 84104
 Nevada contractor's license number issued by the State Contractor's Board 0021976
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2376
 Signed _____
 By driller performing actual drilling on site or contractor
 Date December 20 2010