

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 113143  
Permit No. \_\_\_\_\_  
Basin 101

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 66321

1 OWNER Singh Gurdeep & Johal Ravinder  
MAILING ADDRESS 1325 S. Taylor Street  
Fallon, NV 89406

ADDRESS AT WELL LOCATION Facility ID: 5-000110 OW-1  
1325 S. Taylor Street Fallon, NV  
Subdivision Name: \_\_\_\_\_ County: Churchill

2 LOCATION SW 1/4 SW 1/4 Sec 31 T 19N N/S R 29 E  
PERMIT/WAIVER No. \_\_\_\_\_  
001-461-09  
Issued by Water Resources Parcel No.

Latitude 14839248.59 UTM E  NAD 27  
Longitude 2568819.96 N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? No  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 13 Feet Depth Cased \_\_\_\_\_ Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4"</u>		<u>Sch 40</u>		

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:  
Type of perforation \_\_\_\_\_ Slot \_\_\_\_\_  
Size of perforation \_\_\_\_\_ 0.02  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS  
Material Used  
From 0 feet to 13 feet Neat Cement  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

6 Additional Notes or Comments  
Used rods to bust out bottom of wells, used tremmie pipe to grout from bottom up. Top off grout and remove surface completions.  
\* Did not have original well construction information.

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 1/17/2011  
Date Completed 1/17/2011

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Cascade Drilling, L.P. Contractor  
Address 3632 Omec Circle Contractor  
Rancho Cordova, CA 95742  
Nevada contractor's license number issued by the State Contractor's Board 73966  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-1991  
Signed [Signature] By driller performing actual drilling on site or contractor  
Date 2/23/2011

STATE ENGINEERS OFFICE  
2011 MAR -4 AM 11:10

RECEIVED

USE ADDITIONAL SHEETS IF NECESSARY  
39.462981°N  
118.78081°W  
NAD 27 TA

(Rev. 05-00)