

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

1 of 2
OFFICE USE ONLY
Log No. 113867
Permit No. _____
Basin 087

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 64328

1 OWNER Dansk Investment Group ADDRESS AT WELL LOCATION 2299 Oddie Blvd
MAILING ADDRESS 6591 Collins Dr STE E-11 SPARKS, NV. 89431
MORCOK, CA. 93021 Subdivision Name: _____ County: Washoe

2 LOCATION SE NE 1/4 Sec 6 T 19 S R 20 E Latitude 39.54497 UTM E _____ NAD 27
PERMIT/WAIVER No. 031-012-24 Longitude -119.7751 N _____ NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? NO
If yes, what is replacement well NO? _____
Is there an existing well log? NO
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 40 Feet Depth Cased 40 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2</u>		<u>SLH. 40</u>	<u>0</u>	<u>40</u>

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____
Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no Top 5'

Existing Perforations:
Type of perforation Manufactured
Size of perforation 020
From 20 feet to 40 feet
From _____ feet to _____ feet
From _____ feet to _____ feet
From _____ feet to _____ feet

If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: N/A
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

5 WATER LEVEL
Static water level 31' feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS
Material Used
From 0 feet to 40 feet Pumped Poured
From _____ feet to _____ feet Pumped Poured

6 Additional Notes or Comments
Well was pressure grouted + top 5' of casing was removed.
MW-12

Neat Cement Fluid Weight 47/10 lbs/gal
Bentonite Grout _____ % bentonite
Date Started 4-21-11
Date Completed 4-21-11




9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Gregg Drilling + Testing Inc. Contractor
Address 950 Howe Rd Martinez, CA 94555 Contractor
Nevada contractor's license number issued by the State Contractor's Board C23-0038113
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2328
Signed [Signature]
Date 5-16-11
By driller performing actual drilling on site or contractor

USE ADDITIONAL SHEETS IF NECESSARY
39.545059° N
119.774507° W
NAD 27 (TA)

STATE DIVISION OF WATER RESOURCES
2011 MAY 18 AM 11:12
RECEIVED

ODDIE BLVD

EL RANCHO



← DRIVEWAY →

LEGEND

-  Monitor Well Location
-  Abandoned or Destroyed Well

SHOPPING CENTER