

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

1 of 2
OFFICE USE ONLY
Log No. 113869
Permit No. _____
Basin φ87

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 64328

1 OWNER Dansk Investment Group
MAILING ADDRESS 6591 Colling Dr STE E-11
Morpark CA 95021

ADDRESS AT WELL LOCATION 2299 Oddie Blvd Sparks, NV 89431
Subdivision Name: _____ County: Washoe

2 LOCATION SE 1/4 NE 1/4 Sec 6 T 19 N R 20 E
PERMIT/WAIVER No. .031-012-24
issued by Water Resources Parcel No.

Latitude 39.54497 UTM E NAD 27
Longitude -119.77561 N NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? NO
If yes, what is replacement well NOI? _____
Is there an existing well log? NO
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 40 Feet 40 Depth Cased 40 Feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4 1/2</u>		<u>SCH-40</u>	<u>0</u>	<u>40</u>

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no Top 5'
If casing was left in place, please show where additional perforations were made:
Additional Perforations:

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet	feet
<u>D56 Manufactured</u>	<u>.020</u>		<u>40</u>		

Type of perforator used: n/a

From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL
Static water level 31 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS
Material Used

From	feet to	feet	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From <u>0</u>	feet to <u>40</u>	feet	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	feet to	feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	feet to	feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	feet to	feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	feet to	feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	feet to	feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

6 Additional Notes or Comments
Well was pressure grouted + top 5' of casing was removed
SVE-7

Neat Cement Fluid Weight 47 1/2 lbs/gal
Bentonite Grout _____ % bentonite
Date Started 4-21-11
Date Completed 4-21-11

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name 61999 Drilling & Testing Inc Contractor
Address 950 Howe Rd Martinez, CA 94553 Contractor
Nevada contractor's license number issued by the State Contractor's Board 623-0038113
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2328
Signed _____
Date 5-16-11
By driller performing actual drilling on site or contractor



USE ADDITIONAL SHEETS IF NECESSARY

39.545059 N
119.774587 W
NAD 27 TA

2 of 2

ODDIE BLVD

EL RANCHO



← DRIVEWAY →



LEGEND

- ⊕ Monitor Well Location
- Abandoned or Destroyed Well

SHOPPING CENTER