

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

1 OF 2  
OFFICE USE ONLY  
Log No. 113870  
Permit No.   
Basin 087

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 64328

1 OWNER Dansk Investment Group  
MAILING ADDRESS 6591 Collins Dr. Ste E-11  
Morro Bay, CA 93021

ADDRESS AT WELL LOCATION 2299 Oddie Blvd  
SPARKS, NV 89431  
Subdivision Name County: Washoe

2 LOCATION NE 1/4 NW 1/4 Sec 6 T 19 N R 20 E  
PERMIT/WAIVER No. 031-012-24  
Issued by Water Resources Parcel No.

Latitude 39.54497 UTM E NAD 27  
Longitude -119.77561 N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NOI?  
Is there an existing well log? NO  
If yes, what is NDWR well log #?

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 40 Feet 40 Depth Cased 40 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why:

Size O.D. (Inches)	Weight/FL (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4 1/2		SCH. 40	0	40

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations: Top 5'

Existing Perforations:  
Type of perforation manufactured  
Size of perforation .020  
From 20 feet to 40 feet

Type of perforator used: N/A  
From feet to feet Number of perfs per linear foot  
From feet to feet Number of perfs per linear foot  
From feet to feet Number of perfs per linear foot  
From feet to feet Number of perfs per linear foot  
From feet to feet Number of perfs per linear foot  
From feet to feet Number of perfs per linear foot

5 WATER LEVEL  
Static water level 31 feet below land surface  
Artesian flow G.P.M. P.S.I.  
Water temperature °F Quality

8 WELL PLUGGING MATERIALS  
Material Used  
From 0 feet to 40 feet  Pumped  Poured  
From feet to feet  Pumped  Poured

6 Additional Notes or Comments  
Well was pressure grouted + top 5' of casing was removed  
MAW-2

Neat Cement Fluid Weight 47/6 lbs/gal  
Bentonite Grout % bentonite  
Date Started 4-21-11  
Date Completed 4-21-11



9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name 6/egg Drilling & Testing Inc Contractor  
Address 950 Howe Rd Martinez, CA 94553 Contractor  
Nevada contractor's license number issued by the State Contractor's Board C23-0039113  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2328  
Signed [Signature] Driller performing actual drilling on site or contractor  
Date 5-16-11

USE ADDITIONAL SHEETS IF NECESSARY  
39.5450590N  
119.7745870W  
NAD 27 (TW)


2011 MAY 18 AM 11:12  
RECEIVED

ODDIE BLVD

EL RANCHO



← DRIVEWAY →



**LEGEND**

- ◆ Monitor Well Location
- Abandoned or Destroyed Well

SHOPPING CENTER