

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

1 of 2

OFFICE USE ONLY
Log No. 113874
Permit No. _____
Basin 087

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 64327

1 OWNER Dansk Investment Group LLC
MAILING ADDRESS 6591 Collins Dr STE E-11
Mesa Park, CA 93021

ADDRESS AT WELL LOCATION 2225 Oddie Blvd
Sparks, NV
Subdivision Name _____ County Washoe

2 LOCATION BE 4 ME 1/4 Sec 6 T 19 R 20
PERMIT/WAIVER No. D31-012-25
Issued by Water Resources Parcel No.

Latitude 39.54497 UTM E NAD 27
Longitude -119.77561 N NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? NO
If yes, what is replacement well NOI? _____
Is there an existing well log? NO
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 40 Feet 40 Depth Cased 40 Feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4</u>		<u>5/8 - 40</u>	<u>0</u>	<u>40</u>

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no TOP 5'

Existing Perforations:
Type of perforation Manufactured
Size of perforation 0.200
From 20 feet to 40 feet
From _____ feet to _____ feet
From _____ feet to _____ feet
From _____ feet to _____ feet

If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: N/A
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

5 WATER LEVEL
Static water level 31 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS
Material Used
From 0 feet to 40 feet Pumped Poured
From _____ feet to _____ feet Pumped Poured

6 Additional Notes or Comments
Well was pressure grouted & top 5' of casing was removed
SVE-2
2011 MAY 18 AM 11:12

Neat Cement Fluid Weight 47/6 lbs/gal
Bentonite Grout _____ % bentonite
Date Started 4-21-11
Date Completed 4-21-11

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Weggs Drilling & Testing Contractor
Address 950 Howe Rd, Martinez, CA 94553 Contractor
Nevada contractor's license number issued by the State Contractor's Board C23-0038113
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2328
Signed [Signature]
Date 5-16-11
By driller performing actual plugging on site or contractor

USE ADDITIONAL SHEETS IF NECESSARY
39.54505° N
119.774507° W
NAD 27 (TA)

ODDIE BLVD

EL RANCHO

MW-7

MW-11

MW-15

MW-2

MW-6/SVE-6

MW-10/SVE-5

AS-5

MW-3

MW-5

AS-2

SVE-2

SVE-7

SVE-1

WALGREENS

AS-1

AS-4

MW-1

MW-4/SVE-4

MW-14

MW-13



JACK IN THE BOX

MW-8

MW-9

MW-12

← DRIVEWAY →



LEGEND

- ◆ Monitor Well Location
- Abandoned or Destroyed Well

SHOPPING CENTER