

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY
Log No. 113876
Permit No. _____
Basin φ87

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 64326

1 OWNER OAKS Investment Group LLC
MAILING ADDRESS 6591 Collins Dr STE E-11
Mesa Park CA 93021

ADDRESS AT WELL LOCATION 2289 ~~W~~ Daddie Blvd
Sparks, NV 89431
Subdivision Name _____ County Washoe

2 LOCATION N 1/4 NE 1/4 Sec 6 T 19 N S R 20 E
PERMIT/WAIVER No. 031-012-21
Issued by Water Resources Parcel No

Latitude 39.544 UTM E NAD 27
Longitude -119.77561 N NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? NO
If yes, what is replacement well NOI? _____

Is there an existing well log? NO
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 40 Feet 40 Depth Cased 40 Feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2</u>		<u>SCH. 40</u>	<u>0</u>	<u>40</u>

If well was not cleaned out to total depth, please explain why: _____

Existing Perforations:

From	Type of perforation	Size of perforation	feet to	feet
	<u>Manufactured</u>	<u>1.020</u>		
			<u>30</u>	<u>40</u>
From				

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no Top 5'

If casing was left in place, please show where additional perforations were made:
Additional Perforations:

From	Type of perforator used:	feet to	feet	Number of perfs per linear foot
	<u>N/A</u>			
From				

5 WATER LEVEL
Static water level 31 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS

6 Additional Notes or Comments
Well was pressure grouted & top 5' was removed.
MW-13

From	feet to	feet	Material Used
<u>0</u>	<u>40</u>	<u>40</u>	<input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured
From	feet to	feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From	feet to	feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From	feet to	feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From	feet to	feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From	feet to	feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

Neat Cement Fluid Weight 47/6 lbs/gal
Bentonite Grout _____ % bentonite
Date Started 4-21-11
Date Completed 4-21-11

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Loiseg Drilling & Testing Inc Contractor
Address 950 Howe Rd Martinez, CA 94553 Contractor
Nevada contractor's license number issued by the State Contractor's Board 023-0038113
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-2328
Signed [Signature] By driller performing actual drilling on site or contractor
Date 5-16-11


USE ADDITIONAL SHEETS IF NECESSARY

39.545054°N
119.774587°W
NAD 27 (TA)



2011 MAY 18 AM 11:21

ODDIE BLVD

EL RANCHO



← DRIVEWAY →



LEGEND

- ◆ Monitor Well Location
- Abandoned or Destroyed Well

SHOPPING CENTER