

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 114058  
Permit No. \_\_\_\_\_  
Basin φ73

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 67129

1 OWNER Richard Sorani ADDRESS AT WELL LOCATION Facility ID - 5-00082  
MAILING ADDRESS P.O. Box 1030 810 Cornell Ave. Lovelock, NV  
Lovelock, NV 89419 Subdivision Name: \_\_\_\_\_ County: Pershing

2 LOCATION NW ¼ SW ¼ Sec 26 T 27N N/S R 31 E Latitude 40°10'42.02"N UTM E  NAD 27  
PERMIT/WAIVER No. 001-128-15 Longitude 118°28'30.79"W N  NAD 83/WGS 84  
*Issued by Water Resources Parcel No.*

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? No  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? Yes  
If yes, what is NDWR well log #? 81722

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 21 Feet Depth Cased 21 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2"		Sch 40	0	21

Existing Perforations:  
Type of perforation \_\_\_\_\_ Slot \_\_\_\_\_  
Size of perforation \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

Type of perforater used: \_\_\_\_\_ Broke out Bottom  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

Material Used  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

6 Additional Notes or Comments

Brake out bottom of well tremmie grout - Concrete top  
RECEIVED  
2011 JUN 24 11:11:49  
STATE ENGINEER OF NV

Neat Cement Fluid Weight 47 lbs/gal  
Bentonite Grout 3 % bentonite  
Date Started 28-Mar-11  
Date Completed 29-Mar-11

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Cascade Drilling, L.P.  
Contractor  
Address 3632 Omec Circle  
Contractor  
Rancho Cordova, CA 95742  
Nevada contractor's license number issued by the State Contractor's Board 73966  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1991  
Signed [Signature]  
By driller performing actual drilling on site or contractor  
Date 25-Apr-11

(Rev. 05-06) USE ADDITIONAL SHEETS IF NECESSARY  
40.178430°N  
118.474239°W  
NAD27  
D.D.