

STATE OF NEVADA  
 DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
 Log No. 114086  
 Permit No. \_\_\_\_\_  
 Basin 212

PRINT OR TYPE ONLY  
 DO NOT WRITE ON BACK

Please complete this form in its entirety in  
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 35154

1 OWNER Bixby Land Co.  
 MAILING ADDRESS 2211 Michelson Dr. Suite 500  
Irvine, California 92612

ADDRESS AT WELL LOCATION 7600 Eastgate Road  
Henderson, Nevada, 89011  
 Subdivision Name: TW-1 County: Clark

2 LOCATION SW 1/4 NE 1/4 Sec 11 T 22 NSR 62 E  
 PERMIT/WAIVER No. N/A 178-11-610-002  
Issued by Water Resources Parcel No.

Latitude 36.051661 UTM E  NAD 27  
 Longitude -115.019539 N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a  
 replacement well was drilled? No  
 If yes, what is replacement well NOI?

Is there an existing well log? No  
 If yes, what is NDWR well log #?

4 EXISTING WELL CONSTRUCTION  
 Depth Drilled unkn Feet Depth Cased 40 Feet

7 WELL PLUGGING PROCEDURE  
 Was well cleaned out to total depth?  yes  no  
 If well was not cleaned out to total depth, please explain why:

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2"		PVC Schedule 40	0	40

Was the well contaminated?  yes  no  
 Was the casing pulled?  yes  no  
 Was the casing over drilled?  yes  no  
 If casing was left in place, please show where additional perforations were made:

Existing Perforations:

Type of perforation	Factory Slotted
Size of perforation <u>25</u> feet to <u>40</u> feet	<u>0.02</u>
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	

Additional Perforations:

Type of perforator used:	Number of perfs per linear foot
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	

5 WATER LEVEL  
 Static water level 33 feet below land surface  
 Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
 Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	Material Used	Pumped	Poured
0	1	Concrete	<input type="checkbox"/>	<input checked="" type="checkbox"/>
1	40	Benonite Chips	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
 Bentonite Grout \_\_\_\_\_ % bentonite  
 Date Started 6/8/2011  
 Date Completed 6/13/2011

6-8-2011 The monitoring well casing separated at the first connection during the pulling.  
 6-13-2011 The monitoring well was over drilled and plugged using 3/8" bentonite chips.

9 DRILLER'S CERTIFICATION  
 This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Richard Erickson  
 Contractor  
 Address 750 S Pilot Road Suite F  
 Contractor  
Las Vegas, Nevada 89119  
 Nevada contractor's license number \_\_\_\_\_  
 issued by the State Contractor's Board  
 Nevada driller's license number issued by the \_\_\_\_\_  
 Division of Water Resources, the on-site driller M-2409  
 Signed Richard Erickson  
 By driller performing actual drilling on site or contractor  
 Date 6/15/2011

DCNR/DWR  
 RECEIVED

JUN 16 2011

LAS VEGAS OFFICE