

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 114096  
Permit No. 31150  
Basin 212

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. \_\_\_\_\_

1 OWNER Holy Spirit Assn Christianity  
MAILING ADDRESS 7966 Haven St.  
Las Vegas NV 89127

ADDRESS AT WELL LOCATION SAME  
Subdivision Name: \_\_\_\_\_ County: CLARK

2 LOCATION SE 1/4 SW 1/4 Sec 9 T 22 N R 61 E  
PERMIT/WAIVER No. R 1519 177 09 403 008  
Issued by Water Resources Parcel No.

Latitude N 36° 02' 40.58" UTM E  NAD 27  
Longitude W 115° 10' 02.63" N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? Yes  
If yes, what is replacement well NOI? 38756  
Is there an existing well log? 16463  
If yes, what is NDWR well log #? 16463

4 EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>7 5/8</u>				

7 PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why:  
Casing Had Rotted Away And Well Collapsed  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:  
Type of perforation \_\_\_\_\_  
Size of perforation \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: n/a  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level 126 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
<u>147</u>	<u>103</u>	<u>3/8 Bentonite</u>	<input type="checkbox"/>	<input type="checkbox"/>
<u>103</u>	<u>+ 1 FT.</u>	<u>Cement Grout</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
Tremie Pipe was Installed To Well and Bentonite 3/8 Coated was Poured down Tremie Pipe until Hole was Filled To 103 Ft. Waited until next Day to Fill with Cement grout giving The Bentonite Time to Swell

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 4-28-11  
Date Completed 4-29-11

DCNR/DWR RECEIVED  
JUN 20 2011

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Redding Drilling & Pump Service  
Address P.O. Box 23120  
Las Vegas, NV 89105  
Nevada contractor's license number 38155  
issued by the State Contractor's Board  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller  
Signed [Signature]  
Date 5-20-11

(Rev. 05-06)

USE ADDITIONAL SHEETS IF NECESSARY

LAS VEGAS OFFICE