

STATE OF NEVADA  
 DIVISION OF WATER RESOURCES  
 WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
 Log No. 114282  
 Permit No. \_\_\_\_\_  
 Basin \_\_\_\_\_

PRINT OR TYPE ONLY  
 DO NOT WRITE ON BACK

Please complete this form in its entirety in  
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 35852

1 OWNER NEVADA POWER COMPANY % LAND ADDRESS AT WELL LOCATION NV ENERGY REID GARDNER  
 MAILING ADDRESS SERV. STA. #9 P.O. BOX 98910 STATION MOAPA NV.  
LAS VEGAS NV 89193 Subdivision Name: \_\_\_\_\_ County: CLARK

2 LOCATION NE 1/4 NW 1/4 Sec 07 T 15 N/S R 66 E Latitude 36.6483936 UTM E \_\_\_\_\_  NAD 27  
 PERMIT/WAIVER No. 04207000001 Longitude 114.6501103 N \_\_\_\_\_  NAD 83/WGS 84

Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? NO  
 If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? NO  
 If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION

Depth Drilled 156 Feet Depth Cased 156 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4</u>		<u>SC440</u>	<u>0</u>	<u>156</u>

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no  
 If well was not cleaned out to total depth, please explain why: PERFORATED

Was the well contaminated?  yes  no  
 Was the casing pulled?  yes  no  
 Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
 Additional Perforations: \_\_\_\_\_

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	To	feet
<u>MACHINE SLOT</u>	<u>020</u>	<u>136</u>	<u>156</u>		

Type of perforator used: BLADE CUTTER

From	feet to	feet	Number of perfs per linear foot
<u>10</u>	<u>156</u>		<u>4</u>

5 WATER LEVEL

Static water level NONE feet below land surface  
 Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
 Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

Material Used

From	feet to	feet	Material	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
<u>0</u>	<u>156</u>		<u>CEMENT GROUT</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments

WELL NO. LMW6  
FACILITY I.D. NO. H-000530

Neat Cement Fluid Weight 94 lbs/gal 5.2  
 Bentonite Grout \_\_\_\_\_ % bentonite

Date Started 7-19-2011  
 Date Completed 7-19-2011

DCNR/DWR  
 RECEIVED  
 JUL 29 2011

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name EAGLE DRILLING Contractor  
 Address 7150 PLACID ST Contractor  
LAS VEGAS NV. 89119  
 Nevada contractor's license number issued by the State Contractor's Board 51266  
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2357  
 Signed Matt Winkler By driller performing actual drilling on-site or contractor  
 Date 7-21-2011

(Rev. 05-06) USE ADDITIONAL SHEETS IF NECESSARY