

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 119669  
Permit No. \_\_\_\_\_  
Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 35992

<b>1 OWNER</b> <u>Public ROW</u> MAILING ADDRESS <u>500 South Grand Central Pkwy</u> <u>Las Vegas, NV</u>	ADDRESS AT WELL LOCATION <u>Public ROW on Boulder Hwy</u> <u>at Boulder Hwy and Dalhart St.</u> Subdivision Name: _____ County: _____
<b>2 LOCATION</b> NW ¼ <u>NW</u> ¼ Sec <u>7</u> T <u>21S</u> N/S R <u>62</u> E PERMIT/WAIVER No. <u>DW-1319A</u> <u>16107199011</u> <small>Issued by Water Resources Parcel No.</small>	Latitude <u>7995445.54</u> UTM E <input type="checkbox"/> NAD 27 Longitude <u>26753958.33</u> N <input checked="" type="checkbox"/> NAD 83/WGS 84

<b>3 TYPE OF WELL</b> <input type="checkbox"/> Domestic <input type="checkbox"/> Irrigation <input type="checkbox"/> Test <input type="checkbox"/> Municipal/Industrial <input type="checkbox"/> Monitor <input type="checkbox"/> Stock	Is this well being plugged because a replacement well was drilled? <u>no</u> If yes, what is replacement well NO? _____	Is there an existing well log? _____ If yes, what is NDWR well log #? _____
---	--	--

**4 EXISTING WELL CONSTRUCTION**  
 Depth Drilled 35 Feet    Depth Cased 35 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	35

*Existing Perforations:*

Type of perforation	Size of perforation	From	To
machine Slot	15	feet to	35 feet

**5 WATER LEVEL**  
 Static water level \_\_\_\_\_ feet below land surface  
 Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
 Water temperature \_\_\_\_\_ °F    Quality \_\_\_\_\_

**6 Additional Notes or Comments**

**Well #10**

**DCNR/DWR  
RECEIVED  
DEC 05 2011  
LAS VEGAS OFFICE**

**7 WELL PLUGGING PROCEDURE**  
 Was well cleaned out to total depth?  yes  no  
 If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
 Was the casing pulled?  yes  no  
 Was the casing over drilled?  yes  no  
 If casing was left in place, please show where additional perforations were made:  
*Additional Perforations:*

*Type of perforator used:*

From	feet to	feet	Number of perfs per linear foot

**8 WELL PLUGGING MATERIALS**

				Material Used	
From	<u>0</u>	feet to	<u>10</u>	feet	Concrete Grout 3/8s <input type="checkbox"/> Pumped <input checked="" type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
 Bentonite Grout \_\_\_\_\_ % bentonite  
 Date Started 9/20/2011  
 Date Completed 9/20/2011

**9 DRILLER'S CERTIFICATION**

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Viking Drillers Inc Contractor  
 Address 801 Northport Dr. Contractor  
Sacramento, CA 95691

Nevada contractor's license number 0034680  
 issued by the State Contractor's Board

Nevada driller's license number issued by the DEW-2361  
 Division of Water Resources, the on-site driller

Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor

Date 11/9/2011

(Rev. 05-06)

**USE ADDITIONAL SHEETS IF NECESSARY**