

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
Log No. 114780  
Permit No. \_\_\_\_\_  
Basin 212

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 36316

1 OWNER Herbst Development llc Long John Silvers Inc Lease ADDRESS AT WELL LOCATION 300 N Boulder Highway  
MAILING ADDRESS 5195 S Las Vegas Blvd South Las Vegas  
NV 89119 Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION NW ¼ NE ¼ Sec 18 T 22S N/S R 63 E Latitude 36.02.29.69 UTM E  NAD 27  
PERMIT/WAIVER No. 8-000664 179-07-811-003 Longitude 114.58.59.59 N  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 70 Feet Depth Cased 70 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6"	pvc	sch 40	0	70

Existing Perforations:  
Type of perforation mechanical  
Size of perforation 0.02  
From 50 feet to 70 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

Type of perforator used: Ripper  
From 45 feet to 70 feet Number of perfs per linear foot 4  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level 63 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	Material Used		
From <u>2'</u>	feet to <u>70</u>	Quich Grout	<input checked="" type="checkbox"/> Pumpe	<input type="checkbox"/> Poured
From <u>0</u>	feet to <u>2'</u>	concrete	<input type="checkbox"/> Pumpe	<input checked="" type="checkbox"/> Poured
From _____	feet to _____		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____	feet to _____		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____	feet to _____		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____	feet to _____		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

6 Additional Notes or Comments

Knock bottom out of well and grouted from bottom up  
Ripped casing due to casing not able to be pulled.

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 12/23/2011  
Date Completed 12/23/2011

**DCNR/DWR  
RECEIVED**  
JAN 03 2012  
**LAS VEGAS OFFICE**  
0861108r lw9

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eagle Drilling Services llc Contractor  
Address 7150 placid street Contractor  
Las Vegas Nv 89119  
Nevada contractor's license number issued by the State Contractor's Board 51266  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2097  
Signed [Signature] By driller performing actual drilling on 2097 contractor  
Date 1/3/2012