

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 115175  
Permit No. 40902  
Basin 059

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 67382

1 OWNER Newmont Mining Corp ADDRESS AT WELL LOCATION Copper Basin south of  
MAILING ADDRESS P O Box 388 Battel mountain NV Newmont P.O. Box 566  
Valmy, Nevada 89438 Subdivision Name: \_\_\_\_\_ County: Lander

2 LOCATION SW 1/4 NE 1/4 Sec 32 T 32 R 44 E Latitude 40° 36' 11" N UTM E \_\_\_\_\_  NAD 27  
PERMIT/WAIVER No. 40902 R-10983 Longitude 117° 02' 28.9" W N \_\_\_\_\_  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? yes  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? yes  
If yes, what is NDWR well log #? 23491

4 EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	Feet
EXISTING CASING SCHEDULE			
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet) To (Feet)
<u>8 5/8</u>	<u>12.74</u>	<u>0.92</u>	<u>0</u> <u>360</u>

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
Additional Perforations: \_\_\_\_\_

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
<u>mill slot</u>	<u>1/8</u>	<u>280</u>	<u>feet to</u>	<u>340</u>

Type of perforator used: None per R-waiver # 40902

From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL

Static water level 65 feet below land surface  
Artesian flow N.O. G.P.M. \_\_\_\_\_ P.S.I. \_\_\_\_\_  
Water temperature cool °F Quality Good

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
<u>0</u>	<u>feet to</u>	<u>360</u>	<u>Neat cement</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments

Well casing left in hole & not perforated due to corrosion, possibility of tool loss if perforation attempted

Neat Cement Fluid Weight 16 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 11-7-11  
Date Completed 11-8-11

40.603056° N  
117.041361° W  
NAD27  
Dec/Deg

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Boart Longyear Nevada Contractor  
Address PO Box 2748 Contractor  
Elko, NV 89803

Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 0073086

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2396

Signed Fermin Luna  
By driller performing actual drilling on site or contractor  
Date 11-8-11

USE ADDITIONAL SHEETS IF NECESSARY

Form 05-08