

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 115228
Permit No. 80389T/71214T
Basin 1378

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 67570

1. OWNER Round Mountain Gold Corp. **DW-50** ADDRESS AT WELL LOCATION Round Mountain Gold Mine
MAILING ADDRESS PO Box 480 **Round Mountain, NV 89045** Round Mountain, NV 89045 **Round Mountain, NV**
Subdivision Name: _____ County: Nye

2. LOCATION SE 1/4 SW 1/4 Sec 19 T10N R44E Latitude _____ UTM E 4283924 NAD 27
PERMIT/WAIVER NO. 80389T (see also 71214T) Longitude _____ N 0492548 NAD 83/WGS 84
Issued by Water Resources Parcel No. _____

3. TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? Yes No
If yes, what is replacement well NOI? _____
Is there an existing well log? Yes No
If yes, what is NDWR well log #? 95851

4. EXISTING WELL CONSTRUCTION
Depth Drilled 875 Feet Depth Cased 865 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
10	26.0	.1875	+2	518

Existing Perforations:
Type of perforation Wire wrap
Size of perforation .125
From 81 feet to 518 feet
From _____ feet to _____ feet

5. WATER LEVEL
Static water level: 82' feet below land surface
Artesian flow: No G.P.M. P.S.I.
Water Temperature: _____ °F Quality _____

6. Additional Notes or Comments
105 3/8" hole plug
6 94lb Cement
50 Abantomite

357' of well previously mined off

Replacement well drilled under NOI 67589, Well log # 115228

7. WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? Yes No
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? Yes No
Was the casing pulled? Yes No
Was the casing over drilled? Yes No
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used:
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

8. WELL PLUGGING MATERIALS
Material Used
From 10 feet to 518 feet Pumped Poured
From _____ feet to _____ feet Pumped Poured

Neat Cement Fluid Weight 15.6 lbs/gal
Bentonite Grout _____ % bentonite

Date Started August 31, 2011
Date Completed September 1, 2011

9. DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Boart Longyear Drilling (CONTRACTOR)
Address 2745 California Ave (CONTRACTOR)
Salt Lake City, Utah 84104
Nevada contractor's license number issued by the State Contractor's Board 0021976
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2239

Signed _____
By driller performing actual drilling on site or contractor
Date September 14, 2011

STATE ENGINEERS OF FLORIDA
92:1114 22 SEP 11 07

(Rev 05-06)

USE ADDITIONAL SHEETS IF NECESSARY

38.705783°N MAG27 D.D.
117.085703°W