

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 115-830
Permit No. 80746T
Basin 137B

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 67572

1. OWNER Round Mountain Gold Corp. **DW-38-R** ADDRESS AT WELL LOCATION Round Mountain Gold
MAILING ADDRESS PO Box 480 **Round Mountain, NV 89045** Round Mountain, NV
Round Mountain, NV 89045 **Subdivision Name:** _____ **County:** Nye

2. LOCATION SW 1/4 NE 1/4 Sec 30 T10N R44E Latitude _____ UTM E 4283260 NAD 27
PERMIT/WAIVER NO. 80746T Parcel No. _____ Longitude _____ N 0493029 NAD 83/WGS 84
Issued by Water Resources

3. TYPE OF WELL Domestic *down casing* Irrigation Test Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? Yes No
If yes, what is replacement well NOI? _____
Is there an existing well log? Yes No
If yes, what is NDWR well log #? 99642

4. EXISTING WELL CONSTRUCTION
Depth Drilled 1010 Feet Depth Cased 1000 Feet
EXISTING CASING SCHEDULE
Size O.D. (Inches) Weight/Ft. (Pounds) Wall Thickness (Inches) From (Feet) To (Feet)
12.75 49.56 .375 +2 930'

Existing Perforations:
Type of perforation _____
Size of perforation _____
From 430' feet to 930' feet
From _____ feet to _____ feet

5. WATER LEVEL
Static water level: N/A feet below land surface
Artesian flow: No G.P.M. _____ P.S.I. _____
Water Temperature: _____ °F Quality _____

6. Additional Notes or Comments
170 bags 3/8" hole plug
27 Abantonite
5 Cement

70' of well was previously mined off.

7. WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? Yes No
If well was not cleaned out to total depth, please explain why:
Well casing was offset at 120 ft. below ground surface. Was not able to drill through the steel, bit was starting a new hole.
Was the well contaminated? Yes No
Was the casing pulled? Yes No
Was the casing over drilled? Yes No
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: N/A
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____
From _____ feet to _____ feet Number of perms per linear foot _____

8. WELL PLUGGING MATERIALS
Material Used
aban-
tonite
From 10 feet to 140' feet Pumped Poured
From _____ feet to _____ feet Pumped Poured
Neat Cement Fluid Weight 15.6 lbs/gal
Bentonite Grout _____ % bentonite

Date Started September 3, 2011
Date Completed September 4, 2011

9. DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Boart Longyear Drilling
(CONTRACTOR)
Address 2745 California Ave
(CONTRACTOR)
Salt Lake City, Utah 84104
Nevada contractor's license number issued by the State Contractor's Board 0021976
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2238
Signed _____
By driller performing actual drilling on site or contractor
Date September 14, 2011

STATE ENGINEERS OFFICE
2011 SEP 22 AM 11:26
RECEIVED