

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 115429  
Permit No. 46729  
Basin 29

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 56283

1 OWNER High Desert Ranch  
MAILING ADDRESS 396 Denio Hwy 140, Winnemucca, NV 89445

ADDRESS AT WELL LOCATION Same  
Subdivision Name: \_\_\_\_\_ County: Humboldt

2 LOCATION SW  SW 1/4 Sec 33 T 44N N/S R 31 E  
PERMIT/WAIVER No. 46729  
Issued by Water Resources Parcel No.

Latitude \_\_\_\_\_ UTM E  NAD 27  
Longitude \_\_\_\_\_ N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? Yes  
If yes, what is replacement well NDI? \_\_\_\_\_

Is there an existing well log? No  
If yes, what is NDWR well log #? 10604

4 EXISTING WELL CONSTRUCTION  
Depth Drilled NA Feet Depth Cased \_\_\_\_\_ Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
		Unknown		

If well was not cleaned out to total depth, please explain why:  
Casing was separated at 120ft and offset or damaged so that we could not advance tools beyond this depth

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:

Type of perforation	Size of perforation	From	To
		feet to	feet

if casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: None

From	To	Number of perfs per linear foot
From	feet to	feet

5 WATER LEVEL  
Static water level 90 feet below land surface  
Artesian flow NA G.P.M. P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	To	Material Used	Pumped	Poured
From	-3 feet to 120 feet	Cement/Sand Grout	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From	feet to		<input type="checkbox"/>	<input type="checkbox"/>
From	feet to		<input type="checkbox"/>	<input type="checkbox"/>
From	feet to		<input type="checkbox"/>	<input type="checkbox"/>
From	feet to		<input type="checkbox"/>	<input type="checkbox"/>
From	feet to		<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
Casing was cut off 3 feet below surface, capped with concrete and backfilled with with native soil.

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 9/6/2005  
Date Completed 9/6/2005

Plug well log # 10604  
Replacement well log 101146

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name AMS Enterprises Contractor  
Address 399 Denio Hwy 140 Contractor  
Winnemucca, NV 89445  
Nevada contractor's license number issued by the State Contractor's Board 58683  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2140

RECEIVED  
2011 JUL 27 AM 10:52  
STATE ENGINEERS OFFICE

Signed TEROD JOHNSON By Terod Johnson  
Date 6/9/2011  
By driller performing actual drilling on site or contractor

(Rev. 05-06)

**USE ADDITIONAL SHEETS IF NECESSARY**

NO GPS