

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 115468  
Permit N  
Basin 103

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 67690-67045

1 OWNER Carson Plains Casino / Market Well ADDRESS AT WELL LOCATION 1380 West Newlands  
MAILING ADDRESS 6996 Highway 50 Dayton, NV 89403 Dayton, NV 89403  
Subdivision Name \_\_\_\_\_ County: Lyon

2 LOCATION NW ¼ SW ¼ Sec 27 T 17N N/S R 22 E Latitude 39.30858 N UTM E  NAD 27  
PERMIT/WAIVER No. (87008)77440 019-181-09 Longitude -119.50693 W N  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL  Domestic  Irrigation  Test  Monitor  Stock  
 Municipal/Industrial  Test  Stock  
Is this well being plugged because a replacement well was drilled? no Is there an existing well log? Yes  
If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NOWR well log #? 13148

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 113 Feet Depth Cased 113 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8.625	16.94	.188	0	113

Existing Perforations:

Type of perforation	Size of perforation	From	To
Factory	3 X 32	0	88
From	108	feet to	feet
From		feet to	feet
From		feet to	feet
From		feet to	feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: Mill Knife  
From 88 feet to 50 feet Number of perfs per linear foot 4  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level 65 feet below land surface  
 Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	To	Material Used	Pumped	Poured
From <u>113</u> feet to <u>0</u> feet		<u>Neat Cement</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From _____ feet to _____ feet			<input type="checkbox"/>	<input type="checkbox"/>
From _____ feet to _____ feet			<input type="checkbox"/>	<input type="checkbox"/>
From _____ feet to _____ feet			<input type="checkbox"/>	<input type="checkbox"/>
From _____ feet to _____ feet			<input type="checkbox"/>	<input type="checkbox"/>
From _____ feet to _____ feet			<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 15.6 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 9/26/2011  
Date Completed 9/26/2011

6 Additional Notes or Comments

Pumped cement from the bottom of the well to the top.  
10/12/2011 - Original well log received by NOWR - log missing.  
Plugs Well Log # 13148

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Parsons Drilling, Inc. Contractor  
Address P.O. Box 1265 Contractor  
Fallon, NV 89407  
Nevada contractor's license number issued by the State Contractor's Board 29084  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1753  
Signed [Signature] By driller performing activities on behalf of contractor  
Date 9/26/2011

39.308666° N 119.505924° W NAD 27

USE ADDITIONAL SHEETS IF NECESSARY