

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 115590
Permit No. _____
Basin 212

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 36525

1 OWNER County of Clark ADDRESS AT WELL LOCATION 6800 E. Russell Rd.
MAILING ADDRESS 500 S. Grand Central Pkwy, Las Vegas, Nv Las Vegas, Nv
Subdivision Name: _____ County: Clark

2 LOCATION SE ¼ SW ¼ Sec 25 T 21S N/S R 62 E Latitude 36.08559N UTM E NAD 27
PERMIT/WAIVER No. 161-25-401-001 Longitude 115.00729W N NAD 83/WGS 84
Issued by Water Resources Parcel No. _____

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? no Is there an existing well log? _____
 Domestic Irrigation Test Stock If yes, what is replacement well NOI? _____ If yes, what is NDWR well log #? _____
 Municipal/Industrial Monitor

4 EXISTING WELL CONSTRUCTION
Depth Drilled 30.5 Feet Depth Cased 30.5 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2"	pvc	sch 40	0	30.5

Existing Perforations:

Type of perforation	Machine Slot
From <u>30.5</u> feet to <u>20</u> feet	<u>0.02</u>
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____
From _____ feet to _____ feet	_____

5 WATER LEVEL
Static water level N/A feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

6 Additional Notes or Comments
_____ **ATTEMPTED TO PULL CASING WAS UNSUCCESSFUL. BROKE BOTTOM OUT AND**
_____ filled from bottom
_____ to top quik grout
_____ **DNDR/DWR RECEIVED**
_____ **SEP 07 2012**
_____ **LAS VEGAS OFFICE**

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

8 WELL PLUGGING MATERIALS
Material Used
From 30.5 feet to 0 feet Quik Grout Pumped Poured
From _____ feet to _____ feet Pumped Poured

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite
Date Started Aug-01-2012
Date Completed Aug-01-2012

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Eagle Drilling Services llc Contractor
Address 7150 placid street Contractor
Las Vegas Nv 89119
Nevada contractor's license number 51266 issued by the State Contractor's Board
Nevada driller's license number issued by the 2399-t1 Division of Water Resources, the on-site driller
Signed [Signature] By driller performing actual drilling on site or contractor
Date 8/3/2012


LAS VEGAS OFFICE

JUL 23 2012

DCNBR/BWR
RECEIVED

DCNBR/BWR
RECEIVED

SEP 07 2012



**AMPAC ISB Re-Injection Well Area Map
DRIT Construction Detour**

**Figure
1**

File: RJW-Area-Map_DRIT_Detour_20090902b 09-02-2009