

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
Log No. 115597  
Permit No. \_\_\_\_\_  
Basin 212

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 36524

1 OWNER CV propco llc ADDRESS AT WELL LOCATION 3680 Tropicana ave Las Vegas NV  
MAILING ADDRESS 1505 S pavilion Center DR  
Las Vegas NV 89135 Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION SW ¼ SW ¼ Sec 20 T 21S N/S R 61 E Latitude 36.06.04.69 UTM E \_\_\_\_\_  NAD 27  
PERMIT/WAIVER No. 8-0001807 162-20-401-009 Longitude 115.11.19.06 N \_\_\_\_\_  NAD 83/WGS 84

Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? no Is there an existing well log? yes  
 Domestic  Irrigation  Test  Stock  
 Municipal/Industrial  Monitor  Stock  
If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? 105719

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 40 Feet Depth Cased 40 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4"</u>	<u>pvc</u>	<u>sch 40</u>	<u>0</u>	<u>40</u>

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforater used: \_\_\_\_\_

From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot

Existing Perforations:  
Type of perforation \_\_\_\_\_  
Size of perforation \_\_\_\_\_

From	feet to	feet
From	feet to	feet

5 WATER LEVEL  
Static water level 32 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	Pumped	Poured
From <u>0</u>	feet to <u>11</u>	feet	<u>concrete</u>	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
From <u>11</u>	feet to <u>40</u>	feet	<u>Bentonite</u>	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
From _____	feet to _____	feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____	feet to _____	feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____	feet to _____	feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____	feet to _____	feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

6 Additional Notes or Comments  
remore well box  
pulled casing  
filled from botton  
To top Bentonite and Concrete  
0031207 well 1

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 8/2/2012  
Date Completed 8/3/2012

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eagle Drilling Services llc Contractor  
Address 7150 placid street Contractor  
Las Vegas Nv 89119  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 51266  
Nevada driller's license number issued by the Division of Water Resources, the On-Site driller 2097  
Signed \_\_\_\_\_  
By driller performing actual drilling on site of contractor  
Date 8/3/2012

**DCNR/DWR  
RECEIVED**

USE ADDITIONAL SHEETS IF NECESSARY  
AUG 08 2012

**LAS VEGAS OFFICE**