

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 115896  
Permit No. \_\_\_\_\_  
Basin 085

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 66132 ✓

1 OWNER Rosalyn & Larry Beck ADDRESS AT WELL LOCATION 2200 Piedras Drive  
MAILING ADDRESS 7004 Murray Ave Sparks, NV  
Seattle, Washington 98131 Subdivision Name Spanish Sp. Vly. County Washoe

2 LOCATION SE 1/4 SE 1/4 Sec 31 T21N N/S R 21E E Latitude 39.63633 UTM E  NAD 27  
PERMIT/WAIVER No. R718 076-391-19 Longitude 119.66281 N  NAD 83/WGS 84

Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? No  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? Yes  
If yes, what is NDWR well log #? 32759

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 338 Feet Depth Cased 338 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>6 5/8</u>	<u>10.78</u>	<u>.156</u>	<u>+2</u>	<u>338</u>

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
Additional Perforations: \_\_\_\_\_

Existing Perforations:

Type of perforation	From	To
<u>Factory</u>	<u>298</u> feet to	<u>318</u> feet
<u>3/32 X 3"</u>		

Type of perforator used: None

From	To	Number of perms per linear foot

5 WATER LEVEL  
Static water level Dry feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	To	Material Used	Pumped	Poured
<u>0</u>	<u>338</u>	<u>Cement/Grout</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
Washoe County Permit #WL120059

RECEIVED  
2012 DEC 18 AM 11:34  
STATE ENGINEERS OFFICE

Plug well log # 32759

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 12-17-12  
Date Completed 12-17-12

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Fundin Pump & Well Service Contractor 89704  
Address 4030 Eastlake Blvd. Washoe Vly. NV Contractor  
Nevada contractor's license number 74720 issued by the State Contractor's Board  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2205  
Signed Verni Hudon By driller performing actual drilling on site or contractor  
Date 12-17-12