

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 115904  
Permit No. \_\_\_\_\_  
Basin 042

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 63830

1 OWNER Union Pacific Rail Road  
MAILING ADDRESS 1400 Douglas St - Stop 1030  
Omaha, NE 68179

ADDRESS AT WELL LOCATION No Address Rail Road Right Away  
Deeth 1 New 1-6094-NV  
Subdivision Name: \_\_\_\_\_ County: Elko

2 LOCATION SE ¼ NE ¼ Sec 26 T 37N N/S R 59 E  
PERMIT/WAIVER No. \_\_\_\_\_  
Issued by Water Resources Parcel No. \_\_\_\_\_

Latitude 41.064668 UTM E \_\_\_\_\_  NAD 27  
Longitude -115.277050 N \_\_\_\_\_  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? No  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 768 Feet Depth Cased 768 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
12			768	0

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
		From		

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

Type of perforator used:	From	feet to	feet	Number of perfs per linear foot
<u>Mill Knife</u>	From <u>100</u>	feet to <u>0</u>	feet	<u>6</u>
	From			

5 WATER LEVEL  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow < 1-gpm G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS  
Material Used

From	feet to	feet	Material	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From <u>768</u>	feet to <u>0</u>	feet	<u>Neat Cement Grout</u>	<input type="checkbox"/>	<input type="checkbox"/>
From				<input type="checkbox"/>	<input type="checkbox"/>
From				<input type="checkbox"/>	<input type="checkbox"/>
From				<input type="checkbox"/>	<input type="checkbox"/>
From				<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
Pressure tremie grouted from the bottom to the surface.

Neat Cement Fluid Weight 15.4 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 9/26/2012  
Date Completed 10/30/2012

RECEIVED  
2012 DEC 17 PM 11:35  
STATE ENGINEERS OF N.D.

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Original Well Log Unknown

Name Boart Longyear Contractor  
Address 7103 W Augusta Ave Contractor  
Glendale, AZ 85303

Nevada contractor's license number issued by the State Contractor's Board 0021976  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2234

Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 12/13/12

(Rev. 05-08) 41.064748 NAD 27  
115.276160

USE ADDITIONAL SHEETS IF NECESSARY