

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 115907
Permit No. _____
Basin 042

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 65277 ✓

1 OWNER Union Pacific Rail Road
MAILING ADDRESS 1400 Douglas St - Stop 1030
Omaha, NE 68179

ADDRESS AT WELL LOCATION No Adress Rail Road Right Away
Deeth 1 New 2-6254-NV
Subdivision Name: _____ County: Eiko

2 LOCATION SE ¼ NE ¼ Sec 26 T 37N N/S R 59 E
PERMIT/WAIVER No. _____
Issued by Water Resources Parcel No.

Latitude 41.06479 UTM E NAD 27
Longitude -115.27679 N NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? NO
If yes, what is replacement well NOI? _____
Is there an existing well log? No
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 19 Feet Depth Cased 19 Feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>24</u>		<u>Corrigatged pipe</u>	<u>19</u>	<u>0</u>

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: None

From	feet to	feet	Number of perfs per linear foot

Existing Perforations:
Type of perforation _____
Size of perforation _____

From	feet to	feet

5 WATER LEVEL
Static water level 11 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS

6 Additional Notes or Comments
Pressure tremie grouted from the bottom to the surface.

RECEIVED
2012 DEC 17 PM 1:33
STATE ENGINEERS OFFICE

Original well log unknown

Material Used

From	feet to	feet	Material Used	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
<u>19</u>	<u>0</u>	<u>0</u>	<u>Neat Cement Grout</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 15.4 lbs/gal
Bentonite Grout _____ % bentonite
Date Started 10/23/2012
Date Completed 10/30/2012

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Boart Longyear
Contractor
Address 7103 W Augusta Ave
Contractor
Glendale, AZ 85303

Nevada contractor's license number _____
issued by the State Contractor's Board 0021976

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2234

Signed [Signature]
By driller performing actual drilling on site or contractor
Date 12/13/12

(Rev. 05-06) 41.064870°N NAD27
115.275900°W

USE ADDITIONAL SHEETS IF NECESSARY