

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
Log No. 115964  
Permit No. \_\_\_\_\_  
Basin 137B

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 69252

1. OWNER **Round Mountain Gold Corp.** ADDRESS AT WELL LOCATION **Round Mtn. Gold Mine, Round Mountain, NV**  
MAILING ADDRESS **P.O. Box 480** **Round Mountain, NV. 89045** *WELL ID: 2007-5* **Subdivision Name:** \_\_\_\_\_ **County:** **Nye**

2. LOCATION **NW¼NE¼ Sec30T10N/ R44E** Latitude \_\_\_\_\_ UTM E **493235**  NAD 27  
PERMIT/WAIVER NO. \_\_\_\_\_ Longitude \_\_\_\_\_ N **4283568**  NAD 83/WGS 84  
*Issued by Water Resources* Parcel No. \_\_\_\_\_

3. TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled?  Yes  No  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log?  Yes  No  
If yes, what is NDWR well log #? **115861**

4. EXISTING WELL CONSTRUCTION

Depth Drilled **1000** Feet Depth Cased **1000** Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2.35	3.65	.154	0	1000

7. WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  Yes  No  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  Yes  No  
Was the casing pulled?  Yes  No  
Was the casing over drilled?  Yes  No

Existing Perforations:

Type of perforation **Factory Slotted**

Size of perforation **.020**

From	feet to	feet
From <b>960</b>	feet to	<b>1000</b> feet
From _____	feet to	_____ feet
From _____	feet to	_____ feet
From _____	feet to	_____ feet
From _____	feet to	_____ feet

If casing was left in place, please show where additional perforations were made:  
Additional Perforations: \_\_\_\_\_

Type of perforator used: \_\_\_\_\_

From	feet to	feet	Number of perfs per linear foot
From _____	feet to	_____ feet	_____
From _____	feet to	_____ feet	_____
From _____	feet to	_____ feet	_____
From _____	feet to	_____ feet	_____
From _____	feet to	_____ feet	_____
From _____	feet to	_____ feet	_____

5. WATER LEVEL

Static water level: **87.35** feet below land surface  
Artesian flow: **N/A** G.P.M. **N/A** P.S.I.  
Water Temperature: \_\_\_\_\_ °F Quality **Fair**

8. WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From <b>0</b>	feet to	<b>1000</b> feet	<b>Neat C.</b>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From _____	feet to	_____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to	_____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to	_____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to	_____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to	_____ feet	_____	<input type="checkbox"/>	<input type="checkbox"/>

6. Additional Notes or Comments  
**28 Bags of Neat Cement**

Neat Cement Fluid Weight **15.6** lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite

Date Started **December 6, 2012**  
Date Completed **December 7, 2012**

9. DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name **Boart Longyear** (CONTRACTOR)  
Address **2745 California Ave.** (CONTRACTOR)  
**SLC., UT. 84104**  
Nevada contractor's license number issued by the State Contractor's Board **0021976**  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller **2258**  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date **December 10, 2012**

RECEIVED  
2012 DEC 14 AM 11:15  
STATE ENGINEERS OFFICE

38.702580°N  
117.077799°W  
NAD83

(Rev 05-06)

USE ADDITIONAL SHEETS IF NECESSARY