

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 116269  
Permit No. \_\_\_\_\_  
Basin 212

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37007

1 OWNER Cassell Beverly J test amentary & clak Roberte lrs  
MAILING ADDRESS 6440 Sky Pointe dr #140-163 LasVegas nv

ADDRESS AT WELL LOCATION 1361 Helm

Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION SW 1/4 NW 1/4 Sec 2 T 22S N35R 61 E  
PERMIT/WAIVER No. 177-02-201-004  
Issued by Water Resources Parcel No. \_\_\_\_\_

Latitude 36.066934 UTM E  NAD 27  
Longitude 115.133998 N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NO? \_\_\_\_\_  
Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 58 Feet Depth Casad 58 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8 5/8	12.15	.134	0	58

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
		From	feet to	feet
		From	feet to	feet
		From	feet to	feet
		From	feet to	feet
		From	feet to	feet

Additional Perforations:

Type of perforator used:	casing was deteriorated	From	feet to	feet	Number of perfs per linear foot
		From	feet to	feet	Number of perfs per linear foot
		From	feet to	feet	Number of perfs per linear foot
		From	feet to	feet	Number of perfs per linear foot
		From	feet to	feet	Number of perfs per linear foot
		From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL  
Static water level 28 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

6 Additional Notes or Comments

Material Used		From	feet to	feet	Material Used	
From	0	feet to	58	feet	Cement Grout	<input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

casing was deteriorated  
tremied  
filled from botton  
To top with Cement Grout

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 1/21/2013  
Date Completed 1/22/2013

DCNR/DWR  
RECEIVED

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eagle Drilling Services llc Contractor  
Address 7150 placid street Contractor  
Las Vegas Nv 89119  
Nevada contractor's license number \_\_\_\_\_  
Issued by the State Contractor's Board 51266  
Nevada driller's license number issued by the \_\_\_\_\_  
Division of Water Resources, the on-site driller 2097  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 1/23/2013

USE ADDITIONAL SHEETS IF NECESSARY

JAN 24 2013  
LAS VEGAS OFFICE  
36.066961  
-115.133168 - NAD 27