STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 116277
Permit No.
Basin 212

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 36823

1 OWNER Caesars Ling LLC
MAILING ADDRESS 1 Caesars Palace dr. Las Vegas, NV 89109-8969

ADDRESS AT WELL LOCATION 3545 S. Las Vegas Blvd Las Vegas, NV
Subdivision Name: County: Clark

2 LOCATION SW ¼ SW ¼ Sec 16 - 21 N/OR 61 E
PERMIT/WAIVER No 162-16-412-002
Issued by Water Resources Parcel No.

Latitude 36.117302
Longitude 115.169771
UTM E
N
☐ NAD 27
☒ NAD 83/WGS 84

3 TYPE OF WELL
☐ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☒ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? NO
If yes, what is replacement well NOI?

Is there an existing well log? 115819
If yes, what is NDWR well log #? 115819

4 EXISTING WELL CONSTRUCTION
Depth Drilled Feet Depth Cased 30 Feet

EXISTING CASING SCHEDULE

Size O.D (Inches)	Weight/Ft (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2"	PVC	Sch 40	0	30

Existing Perforations:
Type of perforation Factory slot
Size of perforation .020

From	10	feet to	30'	feet
From		feet to		feet
From		feet to		feet
From		feet to		feet
From		feet to		feet

5 WATER LEVEL
Static water level 19' feet below land surface
Artesian flow G.P.M. P.S.I.
Water temperature °F Quality

6 Additional Notes or Comments

Footing for the building had been dug out and around well so we could not get drill rig over hole.
So we used a sky lift fork lift to pull pipe.
First we knocked the bottom plug off then poured holeplug inside pipe as we pulled it.

DCNR/DWR
RECEIVED
DEC 07 2012

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☐ yes ☒ no
If well was not cleaned out to total depth, please explain why: Could not get rig over hole. Skylift was used to pull pipe the grouted.

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☒ yes ☐ no
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:
Additional Perforations
Type of perforator used:

From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot
From		feet to		feet	Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

					Material Used		
From	10	feet to	30	feet	holeplug	☐ Pumped	☒ Poured
From	0	feet to	10	feet	cement	☐ Pumped	☒ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured
From		feet to		feet		☐ Pumped	☐ Poured

Neat Cement Fluid Weight lbs/gal
Bentonite Grout % bentonite
Date Started 11/30/12
Date Completed 11/30/12

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Elite Drilling Inc.
Contractor
Address 4255 W. Post rd.
Contractor
Lasvegas, NV 89118
Nevada contractor's license number issued by the State Contractor's Board 0054931
Nevada driller's license number issued by the Division of Water Resources, the on-site driller M-1869
Signed [signature]
By driller performing actual drilling on-site or contractor
Date 11/30/12

USE ADDITIONAL SHEETS IF NECESSARY

LAS VEGAS OFFICE

36.117331
-115.168938 NAD27

(NSPO 3-08) (O) 627A