

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 116594
Permit No. 63987
Basin plb

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. **67562**

1. OWNER **Newmont Mining Corporation**
MAILING ADDRESS **1655 Mountain City Hwy.
Eiko, NV 89801**

ADDRESS AT WELL LOCATION **Leeville Minesite
NW of Carlin, NV**
Subdivision Name: _____ County: **Eureka**

2. LOCATION **SW¼SW¼ Sec2T35N/ R50E**
PERMIT/WAIVER NO. **R-678 / 63987**
Issued by Water Resources Parcel No. _____

Latitude _____ UTM E **556384** NAD 27
Longitude _____ N **4531591** NAD 83/WGS 84

3. TYPE OF WELL
 Domestic **Dewatering** Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? Yes No
If yes, what is replacement well NOI? _____

Is there an existing well log? Yes No
If yes, what is NDWR well log #? **88908**

4. EXISTING WELL CONSTRUCTION
Depth Drilled **2510** Feet Depth Cased **2505** Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
40	210.9	.500	0	35
34	178.9	.500	0	1261
<u>24</u>	94.62	.375	0	2505

Existing Perforations:
Type of perforation **Louver**
Size of perforation **.125**

From	404	feet to	424	feet
From	744	feet to	764	feet
From	1084	feet to	1104	feet
From	1504	feet to	2505	feet
From		feet to		feet

5. WATER LEVEL
Static water level: **2260** feet below land surface
Artesian flow: _____ G.P.M. _____ P.S.I.
Water Temperature: _____ °F Quality _____

6. Additional Notes or Comments
Materials used:
6738 cu. ft. Neat cement
18-5/8" OD aggregate liner installed to 1579'
Bgs cemented in place

40.935409° N
116.330246° W
NAD27

STATE ENGINEERS OFFICE
RECEIVED
2011 SEP -6 AM 11:52

7. WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? Yes No
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? Yes No
Was the casing pulled? Yes No
Was the casing over drilled? Yes No
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: **Holte 10"**

From	1150	feet to	1520	feet	Number of perfs per linear foot	36
From		feet to		feet	Number of perfs per linear foot	
From		feet to		feet	Number of perfs per linear foot	
From		feet to		feet	Number of perfs per linear foot	
From		feet to		feet	Number of perfs per linear foot	
From		feet to		feet	Number of perfs per linear foot	

8. WELL PLUGGING MATERIALS

Material Used
Neat cement

From	0	feet to	2505	feet	<input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From		feet to		feet	<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

Neat Cement Fluid Weight **15.9** lbs/gal
Bentonite Grout _____ % bentonite

Date Started **August 1, 2011**
Date Completed **August 26, 2011**

9. DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name **Boart Longyear Drilling Services**
(CONTRACTOR)
Address **2745 California Ave**
(CONTRACTOR)
Salt Lake City, Utah 84104
Nevada contractor's license number issued by the State Contractor's Board **0021976**
Nevada driller's license number issued by the Division of Water Resources, the on-site driller **2085**

Signed _____
By driller performing actual drilling on site or contractor
Date **August 31, 2011**