

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 117402  
Permit No. \_\_\_\_\_  
Basin 102

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 66611

1 OWNER Ronald Mossis  
MAILING ADDRESS 1575 Quince Silver Springs NV

ADDRESS AT WELL LOCATION 1575 Quince Silver Springs

2 LOCATION nw 1/4 SE 1/4 Sec 31 T 18N N/S R 25 E  
PERMIT/WAIVER No. Dom13-35 1705108  
Issued by Water Resources Parcel No.

Subdivision Name: \_\_\_\_\_ County: Lyon  
Latitude 39 2 938 UTM E  NAD 27  
Longitude 119 13 214 N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? 65924  
Is there an existing well log? 64939  
If yes, what is replacement well NOI? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 120 Feet Depth Cased 120 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
65/8	15	2.19	1	120

If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:

Type of perforation	Size of perforation	From	To
torch cut	16-Mar	112 feet	117 feet

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

Type of perforator used:	From	To	Number of perfs per linear foot
Mills Knife	112 feet	50 feet	4

5 WATER LEVEL  
Static water level 48 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

6 Additional Notes or Comments

*REC'D  
2013 AUG -7 PM 2:14  
STATE ENGINEERS OFFICE*

NAD27  
39.382268° N  
119.219239° W

Plugs well log # 64939  
Replaced by well log # 112401

Material Used	From	To	Material Used	
Bent chips	120 feet	20 feet	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
cement grout	20 feet	0 feet	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
			<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 7/10/2013  
Date Completed 7/10/2013

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Blain Drilling  
Contractor  
Address PO Box 1255 CC NV 89702  
Contractor

Nevada contractor's license number issued by the State Contractor's Board 46498A  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2134

Signed [Signature]  
By driller performing actual drilling on site or contractor  
Date 8/6/2013