

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**

Log No. 117419

Permit No. \_\_\_\_\_

Basin Φ33A

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 68233

1 OWNER Richard & Jean Williams ADDRESS AT WELL LOCATION 2555 Kings River Rd  
 MAILING ADDRESS PO Box 156 Orvada, Nv 89425  
 2 LOCATION SE 1/4 SW 1/4 Sec 29 T 43N 37 E Subdivision Name: williams ranch County: Humboldt  
 PERMIT/WAIVER No. 003-401-18 Latitude UTM E 430118E  NAD 27  
 Longitude N 4602494N NAD 83/WGS 84

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? yes

If yes, what is replacement well NOI? 68232

Is there an existing well log? no

If yes, what is NDWR well log #? n/a

4 EXISTING WELL CONSTRUCTION

Depth Drilled 0 Feet Depth Cased 120 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>8</u>		<u>.188</u>	<u>0</u>	<u>120</u>

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no

If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  no  yes

Was the casing pulled?  no  yes

Was the casing over drilled?  no  yes

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet

If casing was left in place, please show where additional perforations were made:

Additional Perforations:

Type of perforator used:	From	feet to	feet	Number of perfs per linear foot
<u>Holte</u>	<u>5</u>	<u>120</u>	<u>feet</u>	<u>8</u>

5 WATER LEVEL

Static water level 72 feet below land surface

Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.

Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	Pumped	Poured
<u>20</u>	<u>128</u>	<u>feet</u>	<u>Bentonite pellets</u>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<u>0</u>	<u>20</u>	<u>feet</u>	<u>cement grout</u>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

6 Additional Notes or Comments

The casing in the old well was deteriorated severely.

Plugs in known well log replaced by log 117419

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal

Bentonite Grout \_\_\_\_\_ % bentonite

Date Started 7/12/2012

Date Completed 7/12/2012

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name High Desert Drilling llc Contractor

Address 4225 E. Mary Way Winnemucca, Nv 89445-8252 Contractor

Nevada contractor's license number issued by the State Contractor's Board 62237

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2364

Signed [Signature] By driller performing actual drilling on site or contractor

Date 8-1-12

RECEIVED  
 AUG-6 AM 11:04  
 STATE ENGINEERS OF NEVADA

(Rev. 05-06)

41.572991°N  
 117.838199°W  
 NAD27

USE ADDITIONAL SHEETS IF NECESSARY