

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S REPORT

OFFICE USE ONLY
Log No. 117454
Permit No. _____
Basin No. 212

PRINT OR TYPE IN BLACK INK ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37060
WELL NAME (if applicable): MW-11

1. OWNER/CLIENT NAME Jose Rios - 7-11
MAILING ADDRESS Po Box 711
Dallas Tx 75221

DETAILED ADDRESS AT WELL LOCATION 7303 S. Las Vegas Blvd.
L.V. NV.
Subdivision Name: _____ County: Clark

2. PLS LOCATION NE 1/4 NE 1/4 8 Sec 22 W/S 61 E
PERMIT/WAIVER NO. 177 08 501 001
Issued by Water Resources Current Parcel No.

Latitude 26° 03' 23.94 UTM E NAD 27
Longitude 115° 10' 24.54 UTM N NAD 83/WGS 84

3. WORKED PERFORMED
 New Well Deepen: Orig WL# _____
 Replacement: Original well log # _____
 Recondition: Original well log # _____

4. PROPOSED USE
 Domestic Irrigation Monitor
 Mining / Dewater Com / Ind Stock
 Test / Other Mun / QM Rec

5. WELL TYPE
 Auger Rotary RVC
 Air Mud Sonic
 Other

6. LITHOLOGIC LOG

Material Encountered	Lost Circ.	Water Strata	From	To	Thick-ness
<u>Silty Sandy clay</u>	<u>-</u>		<u>0</u>	<u>25</u>	<u>25'</u>
<u>Silty sand</u>			<u>25</u>	<u>30</u>	<u>30</u>
<u>Silty clay</u>			<u>30</u>	<u>49</u>	<u>19</u>
<u>Caliche</u>			<u>49</u>	<u>78</u>	<u>29</u>
<u>Silty Sandy gravel</u>			<u>78</u>	<u>95</u>	<u>17</u>
<u>Sandy - Gravel</u>			<u>95</u>	<u>141</u>	<u>46</u>

9. WELL CONSTRUCTION
Depth Drilled: 141 Feet Depth Cased: 141 Feet
HOLE DIAMETER (BIT SIZE)
From 10.25 Inches To 141 Feet
Inches Feet
Inches Feet

CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4</u>	<u>2.118</u>	<u>.188</u>	<u>5</u>	<u>101</u>
<u>4</u>	<u>2.118</u>	<u>.188</u>	<u>101</u>	<u>141</u>

PERFORATIONS:
Type of perforation: Factory
Size of perforation: 020
From 101 Feet To 141 Feet
From _____ Feet To _____ Feet
From _____ Feet To _____ Feet

ANNULAR MATERIALS
 Sanitary Seal 98' to 101' Pumped Poured
 Neat Cement _____ to _____ Pumped Poured
 Cement Grout _____ to _____ Pumped Poured
 Concrete Grout _____ to _____ Pumped Poured
 Bentonite Chips 98' to 101' Pumped Poured
 Bentonite Grout 1' to 98' Pumped Poured
 15 % 20 % Other, explain: _____
 Gravel Pack [> 0.2 in.] _____ to _____ Pumped Poured
 Sand Pack [< 0.2 in.] 98 to 101 Pumped Poured
 Other, explain: _____ to _____ Pumped Poured

Date started: 6-4, 20 13
Date completed: 6-5, 20 13

7. WATER QUALITIES
Static water level: 81 Feet below land surface
Artesian Flow: _____ G.P.M. _____ P.S.I.
Water Temperature: _____ ° Fahrenheit
Water Quality: clear

8. WELL TEST DATA

Test Method:	G.P.M.	Draw Down (Feet Below Static)	Recorded Time (Hours)
<input type="checkbox"/> Bailer <input type="checkbox"/> Pump <input type="checkbox"/> Air Lift			

10. DRILLER'S CERTIFICATION
This well was drilled under my supervision. This report is true to the best of my knowledge.
Name National EWP Contractor
Address 152 Laguna Landing Henderson NV 89002 Contractor
Nevada contractor's license number as issued by the State Contractor's Board: 0075355
Nevada well driller's license number as issued by the Nevada Division of Water Resources (on-site driller): 2492
Signed: Paul J. Ems
By driller performing actual drilling on site or contractor
Date: _____

36.05665
-115, 173483