

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 117567  
Permit No. \_\_\_\_\_  
Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 37667

1 OWNER Calnev Pipeline Co%G. Gallina ADDRESS AT WELL LOCATION 5049 N. Sloan Ln  
MAILING ADDRESS 1100 Town & Country Rd TTMW-6 Unincorp County  
Orange, CA 92868-4600 Subdivision Name: County: Clark

2 LOCATION NE ¼ SE ¼ Sec 33 T 19S N/S R 62 E Latitude 36 15'07.09"N UTM E  NAD 27  
PERMIT/WAIVER No. 123-33-701-004 Longitude 115 02'51.47"W N  NAD 83/WGS 84  
*Issued by Water Resources Parcel No.*

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? NO Is there an existing well log? N/A  
 Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock If yes, what is replacement well NOI? If yes, what is NDWR well log #?

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 125 Feet Depth Cased 125 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4.5		Sch 40	0	125

Existing Perforations:

Type of perforation	Factory Slotted
Size of perforation <u>0.01</u>	
From <u>85</u> feet to <u>125</u> feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	

5 WATER LEVEL  
Static water level 76 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

6 Additional Notes or Comments

DCNR/DWR/SNBO RECEIVED  
MAY 03 2013

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why:

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	Material Used	Pumped	Poured
0	2	Concrete	<input type="checkbox"/>	<input checked="" type="checkbox"/>
2	125	Cement Grout	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 94/5.2 lbs/gal  
Bentonite Grout 20 % bentonite  
Date Started 1-May  
Date Completed 5/1/2013

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Cascade Drilling L.P. Contractor  
Address 4590 Copper Sage St Contractor  
Las Vegas, NV 89115  
Nevada contractor's license number issued by the State Contractor's Board C23-0073966  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2381  
Signed [Signature]  
Date 5-3-13  
*By driller performing actual drilling on site or contractor*