

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY
Log No. 117859
Permit No. V109179
Basin 105

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 69901

1 OWNER Flying Eagle Ranch
MAILING ADDRESS 850 Flying Eagle Rd GV NV 89460

ADDRESS AT WELL LOCATION Carson River Basin

2 LOCATION SE ¼ SW ¼ Sec 13 T 12N N/S R 19 E
PERMIT/WAIVER No. R742 1219-13-000-032
Issued by Water Resources Parcel No.

Subdivision Name: _____ County: Douglas
Latitude 38 53.846 UTM E NAD 27
Longitude 119 48.040 N NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? yes
If yes, what is replacement well NO? 69899

Is there an existing well log? no
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 60 Feet Depth Cased 60 Feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
3			+2	60

If well was not cleaned out to total depth, please explain why: _____

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
		From	feet to	feet
		From	feet to	feet
		From	feet to	feet
		From	feet to	feet

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no

If casing was left in place, please show where additional perforations were made:
Additional Perforations:

Type of perforator used:	N/A		
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL
Static water level Flowing feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS

6 Additional Notes or Comments
Casing would not pull
Pumped thru Trime neat cement from bottom to top.

		Material Used			
From	<u>0</u> feet to <u>60</u> feet	Neat	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured	
From	_____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured	
From	_____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured	
From	_____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured	
From	_____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured	
From	_____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured	

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite
Date Started 8/5/2013
Date Completed 8/5/2013

Vertical stamp: DIVISION OF WATER RESOURCES

Replaced by 117858
Plug unknown well by
NAD 83
38.847527N
119.800489W

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Blain Drilling Contractor
Address PO Box 1255 CC NV 89702 Contractor

Nevada contractor's license number issued by the State Contractor's Board 46498A
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2134

Signed [Signature] By driller performing actual drilling on site or contractor
Date 8/10/2013