

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 117923  
Permit No. \_\_\_\_\_  
Basin 051

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 68670

1 OWNER Newmont Mining ADDRESS AT WELL LOCATION Gold Quarry  
MAILING ADDRESS US Natl. City Hwy 6 miles n. of Carlin  
Elko, NV 89803 Subdivision Name: \_\_\_\_\_ County: Eureka

2 LOCATION NW 1/4 SW 1/4 Sec 7 T 33N R 52 E Latitude \_\_\_\_\_ UTM E 0569300  NAD 27  
PERMIT/WAIVER No. NEV 88011 Longitude \_\_\_\_\_ N 4512164  NAD 83/WGS 84

Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? YES  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 100 Feet Depth Cased 100 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4"</u>		<u>sch 80</u>	<u>0</u>	<u>100</u>

Existing Perforations:

From	Type of perforation	Size of perforation	feet to	feet
	<u>Slotted</u>	<u>0.020</u>	<u>80</u>	

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

From	Type of perforator used:	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL  
Static water level 53 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I. \_\_\_\_\_  
Water temperature Cold °F Quality good

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
<u>100</u>	<u>28</u>	<u>28</u>	<u>smooth port 30</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<u>28</u>	<u>21</u>	<u>21</u>	<u>3/8 hole plug</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<u>21</u>	<u>0</u>	<u>0</u>	<u>neat cement</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
BPWA

2012 MAR 25 AM 11:31

Neat Cement Fluid Weight 15.2 lbs/gal  
Bentonite Grout 30 % bentonite  
Date Started 1/31/12  
Date Completed 1/31/12

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Boart Longyear Nevada Contractor  
Address PO Box 2748 Contractor  
Elko, NV 89803

Nevada contractor's license number issued by the State Contractor's Board 0073086  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2436

Signed T. B. Bailey  
By driller performing actual drilling on-site or contractor  
Date 2-8-2012

NAD 27 40.759423°N, 116.179000°W